

KMRL DOCUMENT INTELLIGENCE PORTAL

Safety Circular S-101

Fictional controlled copy · Issued 18 August 2026 · Department: Safety/Compliance

Subject: Platform evacuation signage and emergency brake isolation review

This fictional circular directs Safety/Compliance and Maintenance/Quality teams to review emergency brake isolation signage after a simulated platform event.

Required action: complete the review by 25 August 2026 and brief station supervisors before the 30 August 2026 drill.

Signal detail: the change is safety-related and should be routed to Safety/Compliance with support from Rolling Stock Engineering.

Distractor: the staff cafeteria menu will change on 21 August 2026; this detail has no operational bearing.

Control	Requirement	Owner
S-101.1	Review emergency brake isolation signage by 25 August 2026	Safety/Compliance
S-101.2	Brief station supervisors before the next drill	Operations
S-101.3	Record corrective evidence in the safety register	Maintenance/Quality

Safety Circular S-101 — scanned supporting page

Safety Circular S-101

Scanned acknowledgement: supervisor initials S-101 / low-contrast copy /

verify the date against the approved circular.

LOW-CONFIDENCE OCR REGION — VERIFY AGAINST SOURCE

SYNTHETIC DEMO DATA — NOT CONFIDENTIAL KMRL DATA

This scanned page is intentionally low quality for OCR-review demonstration. The amber low-confidence state must remain visible in the portal.