DAMAGE ASSESSMENT REPORT

Analysis Complete

AI-generated repair cost estimate in ₹ INR with pre-approval recommendation

Pre-Approval: Review

The cost of repair is high relative to the age of the vehicle. For an older Subaru in India, parts availability may be an issue, potentially leading to a 'Total Loss' if parts exceed 70% of Insured Declared Value (IDV).

Confidence: **High** Est. Repair: **15 days** Drivable: **No**

Uploaded Image

Vehicle Information

Make/Model	Subaru Forester (Imported/Old Gen)
Color	Silver
Type	SUV

Severity Overview

Overall Severity

SEVERE

8 / 10

> Front-end collision resulting in major structural and cosmetic damage. The impact has compromised the crumple zones (hood), lighting, cooling system, and front structural supports.

Damaged Parts Identified

7 parts

Hood/Bonnet

HIGH

deformation

Severe crumpling and buckling across the entire panel, hinges likely misaligned.

Front Bumper

CRITICAL

shatter

Entire front bumper cover is missing or completely destroyed.

Left Headlight Assembly

CRITICAL

shatter

Complete destruction of the lens and internal housing.

Front Grille

CRITICAL

shatter

Missing/destroyed along with the bumper.

Radiator Support / Crossmember

HIGH

deformation

Structural front support beam is exposed and appears bent, likely affecting cooling system alignment.

Left Front Fender

MEDIUM

dent

Deformation at the leading edge where it meets the headlight and bumper.

Cooling System (Radiator/Condenser)

HIGH

deformation

Visible impact damage to the radiator fins and condenser units.

Cost Estimation (INR ₹)

PART	ACTION	PART COST (₹)	LABOR HRS	LABOR COST (₹)	SUBTOTAL (₹)
Hood Assembly	REPLACE	₹28,000	5h	₹3,200	**₹31,200**
Front Bumper Cover	REPLACE	₹14,000	3h	₹1,600	**₹15,600**
Headlight Assembly (Left)	REPLACE	₹12,000	1h	₹800	**₹12,800**
Radiator & Condenser Kit	REPLACE	₹22,000	6h	₹4,000	**₹26,000**
Front Grille & Emblems	REPLACE	₹6,500	1h	₹600	**₹7,100**
Front Crossmember/Support	REPAIR	₹0	12h	₹8,500	**₹8,500**
Left Front Fender	REPLACE	₹9,500	4h	₹2,400	**₹11,900**

PARTS
₹92,000

LABOR
₹21,100

PAINT & FINISH
₹18,000

Rs
TOTAL ESTIMATED
₹131,100

Additional Notes

Since Subaru has limited presence in India, parts may need to be sourced from specialized importers or secondary markets, which could increase lead times and costs. Internal engine damage cannot be ruled out until the radiator support is dismantled.