Fe-C Problem 1 | Problems T4_PhaseDiagrams II.pdf #1 | Fe-C · hypoeutectoid steel

Phases and Microconstituents of a 0.5 % C Steel

Original statement · Problems T4_PhaseDiagrams II.pdf

1.- For a Fe-C alloy with C_0 = 0.5%C, at the following temperatures: T_1 = (1147+ΔT)ºC; T_2 = (1147-ΔT)ºC; T_3 = 900ºC; T_4 = (727+ΔT)ºC; T_5 = (727-ΔT)ºC. a) Indicate the phases present, their chemical composition and their mass fraction. b) Indicate the micro constituents, their chemical composition and their mass fraction at T_5.

Official Solution: a) T_1, T_2, and T_3: C_γ = 0.5% C, w_γ = 1; T_4: C_α = 0.022% C, C_γ = 0.76% C, w_α = 0.35; T_5: C_α = 0.022% C, C_{Fe_3C} = 6.7% C, w_α = 0.93; b) $w_{\alpha'}$ = 0.35, $w_{\alpha,E}$ = 0.58, w_{Fe_3C} = 0.07

PHASE 1 · HYPOTHESES & PARAMETERS

1. **Equilibrium cooling** on the metastable Fe-Fe3C diagram of the sheet (the diagram of Session 9 Slide 4): C_α = 0.022 % C, eutectoid 0.76 % C at 727 °C, cementite 6.67 % C.
2. $C_0 = 0.5 < 0.76$: a **hypoeutectoid steel** [Session 9 Slide 14]; its solidus is far above 1147 °C, so at T_1, T_2 and T_3 it is fully austenitic.
3. The microconstituents below 727 °C are proeutectoid ferrite and pearlite [Session 9 Slide 14].

Temperature	Region	Phase compositions (% C)
T_1, T_2, T_3	γ	0.5
T_4 = 727 + ΔT	α + γ	α 0.022, γ 0.76
T_5 = 727 − ΔT	α + Fe_3C	α 0.022, Fe_3C 6.67

PHASE 2 · FRAMES & STRATEGY

Frame: the Fe-Fe3C diagram (wt% C, °C); each temperature is one horizontal tie line, so no change of basis is needed. Phases from the lever rule [Session 7 Slide 16]; microconstituents from the short tie line α-eutectoid (0.022-0.76), exactly as in the 0.3 % C example of the slides [Session 9 Slide 18].




Figure 27. Fe-0.5 % C: γ at T_1, T_2 and T_3; α (0.022) + γ (0.76) just above 727 °C; α + Fe_3C just below it. Temperatures 1147 ± ΔT and 727 ± ΔT are drawn slightly apart.

PHASE 3 · STEP-BY-STEP DERIVATION

a) Phases T_1, T_2, T_3: austenite only, $C_\gamma = 0.5$ % C, $W_\gamma = 1$.

T_4 (length $0.76 - 0.022 = 0.738$):

$$W_\alpha = \frac{C_\gamma - C_0}{C_\gamma - C_\alpha} = \frac{0.76 - 0.5}{0.738} = \frac{0.26}{0.738} = 0.352 \qquad W_\gamma = \frac{0.5 - 0.022}{0.738} = \frac{0.478}{0.738} = 0.648$$

T_5 (length $6.67 - 0.022 = 6.648$):

$$W_\alpha = \frac{6.67 - 0.5}{6.648} = \frac{6.17}{6.648} = 0.928 \qquad W_{\mathrm{Fe_3C}} = \frac{0.5 - 0.022}{6.648} = \frac{0.478}{6.648} = 0.072$$

b) Microconstituents at T_5 The ferrite present at T_4 is the proeutectoid ferrite, and the austenite present at T_4 (0.76 % C) becomes pearlite:

$$W_{\alpha'} = 0.352 \qquad W_{\text{pearlite}} = 0.648$$

Inside the pearlite: eutectoid ferrite $W_{\alpha,E} = W_{\alpha} - W_{\alpha'} = 0.928 - 0.352 = 0.576$ and cementite $W_{\text{Fe}_3\text{C}} = 0.072$.




Figure 28. Fe-0.5 % C below 727 °C: proeutectoid ferrite (35 %) and pearlite (65 %).

PHASE 4 · CHECKS & INTERPRETATION

- $0.576 + 0.072 = 0.648 = W_{\text{pearlite}}$, and $0.648 \times 0.889 = 0.576$ (pearlite is 88.9 % ferrite, Session 9 Slide 13) .
- Mass balance at T_5: $0.928 \times 0.022 + 0.072 \times 6.67 = 0.020 + 0.480 = 0.50$ % C .
- Limits: at $C_0 = 0.022$ there is no pearlite; at $C_0 = 0.76$ there is no proeutectoid ferrite.

Check against the official solution

All values agree with the key (0.35; 0.93; 0.35, 0.58, 0.07). The key writes C_{Fe_3C} = 6.7 % C; the 6.67 % C of the slides gives the same rounded results.