Fe-C Problem 10 | Problems T4_PhaseDiagrams II.pdf #10 | Fe-C · pearlite limits

Fe-Cementite Questions and Pearlite Limits

Original statement · Problems T4_PhaseDiagrams II.pdf, p. 3

10.- Using the Fe-cementite phase diagram, indicate: a) What real alloy or alloys comply the following conditions W_α = 0.267 at 727 – ΔT ºC? b) What is the maximum and minimum content (mass fraction W) of pearlite in a steel? Explain why. c) Indicate the invariant points that appear in the diagram and explain which microconstituents are formed during cooling. d) For the alloys with 1.5% C and 3% C, indicate the microconstituents and if the mass fraction of them changes on cooling in the range between 1148 ºC and 727 + ΔT ºC.

Official Solution: a) C_0 = 4.9% C; b) Max: 100% for C_0 = 0.76%C; min: 0% for C_0 < 0.022%C; d) 1.5% C; T_1: w_γ = 1, T_2: w_{Fe_3C} 0.12, w_γ = 0.88; 3% C; T_1: w_γ = 0.6, w_L = 0.4, T_2: $w_{\gamma total}$ = 0.62, $w_{Fe_3C\,Total}$ = 0.38, $w_{Fe_3C\,secondary}$ = 0.20

PHASE 1 · HYPOTHESES & PARAMETERS

1. Equilibrium, Fe-Fe3C diagram [Session 9 Slides 4, 10].
2. Below 727 °C every alloy is α (0.022) + Fe3C (6.67); one ferrite fraction gives one composition.
3. "Steel" = up to 2.14 % C [Session 9 Slide 4].

PHASE 2 · FRAMES & STRATEGY

The lever rule on the α-Fe3C tie line (a), the short tie line through the eutectoid point (b), the invariant lines (c) and the tie lines at 1148 °C and 727 + ΔT (d) [Session 7 Slides 16, 32].




Figure 39. The alloy with 26.7 % α just below 727 °C lies at about 4.9 % C, a hypereutectic cast iron.

PHASE 3 · STEP-BY-STEP DERIVATION

a) Alloy with W_α = 0.267

$$C_0 = 6.67 - 0.267 \times (6.67 - 0.022) = 6.67 - 0.267 \times 6.648 = 6.67 - 1.775 = 4.895 \approx 4.9\ \%\,\mathrm{C}$$

Only **one** alloy: a hypereutectic cast iron.

b) Pearlite in steels Pearlite is the austenite of 0.76 % C present just above 727 °C.

- **Maximum, 100 %**, for the eutectoid steel, C_0 = 0.76 % C: all of it is austenite of eutectoid composition.
- **Minimum, 0 %**, for $C_0 \leq 0.022$ % C: the alloy never crosses the eutectoid line inside the α + γ field (it stays α).
- Between them, hypoeutectoid: $W_{\text{pearlite}} = (C_0 - 0.022)/(0.76 - 0.022)$; hypereutectoid: $W_{\text{pearlite}} = (6.67 - C_0)/(6.67 - 0.76)$, which at the steel limit (2.14 % C) is $4.53/5.91 = 0.77$.

c) Invariant points and their products on cooling [Session 9 Slide 10]

- **Peritectic, 1493 °C:** $\delta\,(0.09) + L\,(0.53) \rightarrow \gamma\,(0.16)$: austenite.
- **Eutectic, 1147 °C:** $L\,(4.3) \rightarrow \gamma\,(2.14) + \mathrm{Fe_3C}$: ledeburite (cast irons).

- **Eutectoid, 727 °C:** $\gamma\,(0.76) \rightarrow \alpha\,(0.022) + \mathrm{Fe_3C}$: pearlite (steels, and the austenite of cast irons).

d) 1.5 % C and 3 % C between 1148 °C and 727 + ΔT 1.5 % C (hypereutectoid steel). At 1148 °C: austenite only, $W_\gamma = 1$. At 727 + ΔT (γ 0.76 / Fe3C 6.67):

$$W_\gamma = \frac{6.67 - 1.5}{5.91} = 0.875 \qquad W_{\mathrm{Fe_3C}} = \frac{1.5 - 0.76}{5.91} = 0.125$$

The microconstituents **change**: proeutectoid cementite appears at A_{cm} and grows to 0.125.

3 % C (hypoeutectic cast iron). At 1148 °C (γ 2.14 / L 4.30): $W_\gamma = 1.30/2.16 = 0.602$, $W_L = 0.398$. At 727 + ΔT (γ 0.76 / Fe3C 6.67):

$$W_{\gamma,\mathrm{total}} = \frac{6.67 - 3.0}{5.91} = \frac{3.67}{5.91} = 0.621 \qquad W_{\mathrm{Fe_3C,total}} = \frac{3.0 - 0.76}{5.91} = \frac{2.24}{5.91} = 0.379$$

The microconstituents (primary austenite and ledeburite) **change** too: the austenite loses carbon and secondary cementite precipitates. The ledeburite brought 0.190 of cementite at 1146 °C (Problem FC09), so the secondary cementite is $0.379 - 0.190 = 0.189$.

PHASE 4 · CHECKS & INTERPRETATION

- (a): $(6.67 - 4.895)/6.648 = 0.267$.
- (d): 1.5 %: $0.875 \times 0.76 + 0.125 \times 6.67 = 0.665 + 0.834 = 1.50$ % C ; 3 %: $0.621 \times 0.76 + 0.379 \times 6.67 = 0.47 + 2.53 = 3.0$ % C .

Check against the official solution

(a), (b) and the 3 % C phases agree with the key (4.9 %; 100 % and 0 %; 0.6/0.4; 0.62/0.38). For 1.5 % C the key gives 0.12/0.88, which is the same as 0.125/0.875 within rounding. The key does not answer part (c).

> DISCREPANCY WITH THE OFFICIAL SOLUTION
> The key gives 0.20 of secondary cementite for the 3 % C alloy. With the values of the diagram, $0.379 - 0.190 = 0.189$ (0.19); the key's 0.20 is not reproduced by any rounding of these data. The computed value is kept.