Vendor of the products: TP-Link


Affected products: TL-WR841ND V11

Hardware Link: <a href="https://www.tp-link.com/us/support/download/tl-wr841nd/v11/#Firmware">https://www.tp-link.com/us/support/download/tl-wr841nd/v11/#Firmware</a>

# **Vulnerability Description**

A buffer overflow vulnerability was discovered in TP-Link TL-WR841ND V11, triggered by the gw parameter at /userRpm/WanDynamicIpV6CfgRpm.htm. This vulnerability allows attackers to cause a Denial of Service (DoS) via a crafted packet.

The interface that triggers the vulnerability



### **POC**

### send

You can see that the router has crashed.

#### Unable to connect

Firefox can't establish a connection to the server at 192.168.0.1.

- The site could be temporarily unavailable or too busy. Try again in a few moments.
- If you are unable to load any pages, check your computer's network connection.
- If your computer or network is protected by a firewall or proxy, make sure that Firefox is permitted to access the web.

Try Again

# Code in httpd

By using IDA to analyze httpd, the program first calls httpGetEnv to retrieve the gw parameter.

The parameters are then passed to the strcpy function without proper security checks, leading to a buffer overflow.