Vendor of the products: TP-Link


Affected products: TL-WR841ND V11

Hardware Link: <a href="https://www.tp-link.com/us/support/download/tl-wr841nd/v11/#Firmware">https://www.tp-link.com/us/support/download/tl-wr841nd/v11/#Firmware</a>

## **Vulnerability Description**

A buffer overflow vulnerability was discovered in TP-Link TL-WR841ND V11, triggered by the pskSecret parameter at /userRpm/WlanSecurityRpm.htm. This vulnerability allows attackers to cause a Denial of Service (DoS) via a crafted packet.


The interface that triggers the vulnerability



## **POC**

send

You can see that the router has crashed.



## **Code in httpd**

By using IDA to analyze httpd, the program first calls httpGetEnv to retrieve the radiuSecret parameter.

The parameter is then passed to the strcpy function without proper security checks, leading to a buffer overflow.