



# **AMP25, AMP50, AMP100**


25,50,100 Ampere Ratings

Hall effect linear sensors. (-40 to +125C)

805/964-9119 FAX 805/967-8789 Box 152, Goleta, CA 93116 e-mail:sales@amploc.com www.amploc.com

		Sensed Current	Vs= +5V	Vs= +5V	+Vs
Sensor		(Amps	ΔVo at peak	Sensitivity	1
Style	Fig.	peak)	rated current **	mV/A**	3
AMP25*	1	25	.925V	37	Sensor U
AMP50	1	50	1.1254V	23	Null Offset=Vs/2
AMP100	1	100	1.9V	19	2
					<u> </u>

<sup>\*\*</sup> proportional to Vs






AMP25 Linear to 60A. AMP50 Linear to 95A. AMP100 Linear to 120A.

**Caution**:Do not reverse supply voltage polarity.

#### **ELECTRICAL CHARACTERISTICS**









## **KEY100,AMP200, AMP300**


 $100\text{A}\,,\,200\text{A}\,,\,300\text{A}\,$  ratings

Hall effect linear current sensors. (-40C to +125C)


805/964-9119 FAX 805/967-8789 Box 152, Goleta, CA 93116 e-mail:sales@amploc.com www.amploc.com

Sensor		Sensed Current (Amps	Vs= +5V ΔVo at peak	Vs= +5V Sensitivity	+Vs
Style	Fig.	peak)	rated current *	mV/A*	3
KEY 100	1	100	1.59V	15.9	Sensor S—Vo
AMP 200	1	200	1.9V	9.5	Null Offset=Vs/2
AMP 300	1	300	2.38V	7.9	2
					<u> </u>

\* proportional to Vs



Mating connector: Samtec SSW-1-03-02-T-S-RA or Molex 5051-04



**Caution**: Do not reverse supply voltage polarity. Do not drop on cement floor.

#### **ELECTRICAL CHARACTERISTICS**

Supply voltage, Vs+4 Supply Current Output Current	. 10mA max. 2mA max.
Offset Voltage, Vo (Sensed I =	0A.). Vs/2±2%
Output Voltage, Vo is proportion	nal to Vs.
Temperature Error	
Null	
Gain	
Temperature Range	40C to +125C
Response Time	3µSec.
Linearity (Full Scale)	
Accuracy (Full Scale)	
,	








**KEY 100** (100A rating)


Hall effect linear current sensors. (-40C to +125C)


805/964-9119 FAX 805/967-8789 Box 152, Goleta, CA 93116 e-mail:sales@amploc.com www.amploc.com

Sensor Style	Fig.	Sensed Current (Amps peak)	Vs= +5V ΔVo at peak rated current *	Vs= +5V Sensitivity mV/A*	+Vs    1	
KEY100	1	100	1.59V	15.9	Sensor	3—Vo
					2 =	☑ Null Offset=Vs/2



Mating connector: Samtec SSW-1-03-02-T-S-RA or Molex 5045-04/AG





**Caution**: Do not reverse supply voltage polarity. Do not drop on cement floor.

### **ELECTRICAL CHARACTERISTICS**

Supply voltage, Vs+4.5 to +8.0 Vdc Supply Current
Offset Voltage, Vo (Sensed I = 0A.). Vs/2±2%
Output Voltage, Vo is proportional to Vs.
Temperature Error
Null
Gain
Temperature Range40C to +125C
Response Time
Linearity (Full Scale)1%
Accuracy (Full Scale) ±2%
,





# **AMP25S, AMP50S, AMP100S**

25,50,100 Ampere Ratings


Hall effect linear sensors. (-40 to +125C)

805/964-9119 FAX 805/967-8789 Box 152, Goleta, CA 93116 e-mail:sales@amploc.com www.amploc.com

		Sensed Current	Vs= +5V	Vs= +5V		+Vs 	
Sensor		(Amps	ΔVo at peak	Sensitivity		1	
Style	Fig.	peak)	rated current **	mV/A**	] [		$\mathbb{I}_3$
AMP25S	1	25	.925 V	37		Sensor	Vo
AMP50S	1	50	1.14V	23	[		Null Offset=Vs/2
AMP100S	1	100	1.9V	19		2	
						÷	

\*\* proportional to Vs






Dimensions: Inches

Terminals: .025 sq., 0.1 spacing.

Weight: 3 grams.



**Caution**: Do not reverse supply voltage polarity.

#### **ELECTRICAL CHARACTERISTICS**

### Temperature Error

ı	Null	
I	Gain	
	Temperature Range	40C to + 125C
I	Response Time	3µSec.
	Linearity (Full Scale)	1%
ı	Accuracy (Full Scale)	±2%
	A.C. Hysterisis Error	0.5%
ı		

