Pressure conversion table

Low PSI	High MPa	High PSI	High bar
0	0	0	0
200	13.8	2000	136.1
400	27.6	4000	272.1
600	41.4	6000	408.2
800	55.2	8000	544.2
1000	69.0	10000	680.3
1200	82.7	12000	816.3
1400	96.5	14000	952.4
1600	110.3	16000	1088.4
1800	124.1	18000	1224.5
2000	137.9	20000	1360.5
2200	151.7	22000	1496.6
2400	165.5	24000	1632.7
2600	179.3	26000	1768.7
2800	193.1	28000	1904.8
3000	206.9	30000	2040.8
3200	220.6	32000	2176.9
3400	234.4	34000	2312.9
3600	248.2	36000	2449.0
3800	262.0	38000	2585.0
4000	275.8	40000	2721.1
4200	289.6	42000	2857.1
4400	303.4	44000	2993.2
4600	317.2	46000	3129.3
4800	331.0	48000	3265.3
5000	344.8	50000	3401.4
5200	358.5	52000	3537.4
5400	372.3	54000	3673.5
5600 5800	386.1 399.9	56000 58000	3809.5 3945.6
6000	413.7	60000	4081.6
6200	427.5	62000	4217.7
6400	441.3	64000	4353.7
6600	455.1	66000	4489.8
6800 7000	468.9 482.7	68000	4625.9 4761.9
7000		70000 72000	4898.0
	496.4		
7400 7600	510.2 524.0	74000 76000	5034.0 5170.1
7800	537.8	78000	5306.1
8000	551.6	80000	5442.2
8200	565.4	82000	5578.2
8400	579.2	84000	5714.3
8600	593.0	86000	5850.3
8800	606.8	88000	5986.4
9000	620.6	90000	6122.4
9200	634.3		
9200	648.1	92000 94000	6258.5 6394.6
9600	661.9	96000	6530.6
9800	675.7	98000	6666.7
10000	689.5	100000	6802.7
10000	000.0	.00000	3002.1