Error of Quadratures Over # of Points, Cost Types, and Delay Parameter Repair, 12 Repair, 23 Repair, 34 10^{-1} 10^{-2} 10^{-3} 0 Decreased Flow, 12 Decreased Flow, 23 Decreased Flow, 34 10^{-1} 10^{-2} 10^{-3} Gauss-Legendre Fejer 1 Increased Current, 12 Increased Current, 23 Increased Current, 34 Fejer 2 Gauss-Lobatto 10^{-1} 10^{-2} 10^{-3} 0 Composite, 12 Composite, 34 Composite, 23 10^{-1} 10^{-2} 10⁻³ 0 10 20 30 10 20 30 10 20 30 Number of Full Model Runs