
UR Manager

New: Flexible Ethernet IP Generator



David Sadek




How to install?


Requirements:


-Windows10.0.19041.0 and higher


- .NET 8.0























Installation

After installing the certificate just double click on the file and install the .msix package