




Defects inspection report no.:


Lugar/site	Parque Eólico de Sines
Núm.IEC/WTG N°	WTG-07
IEC tipo/WTG type	Vestas V90
Año de construcción/Year of construction	2018

2. Photo Documentation



☒ Insert Images



Corrosão na escada











Desgaste no ponto de ancoragem





GENERAL SERVICE S.L.
INDUSTRIAL CLIMBING & MAINTENANCE
GS-CLIMBING.COM



General Service S.L.
<http://gs-climbing.com>

C/Calzada N°23
Edif. Panalmedina, Bajo
29770 Torrox/España/de Málaga

Contacts:
Portugal & Europa:
info@gs-climbing.com
00351 919411147
0049 1774826175



**GENERAL
SERVICE**
CALLE CALZADA N 23
EDIF. PANALMEDINA, BAJO
29770 TORROX/MÁLAGA/SPAIN

3. Additional Fields

Inspector	João Silva
Empresa	GS Climbing
Data da Inspeção	2025-12-22
Condições Meteorológicas	Vento moderado
Acesso	Normal
Urgência	Média
Observações Gerais	Necessária intervenção nos próximos 30 dias