

FIRE PREVENTION NORTHERN DIVISION

GUIDE TO COMPLETION OF FIRE REPORTS

		Description	Example
1)	Type of call	This refers to the nature of the call	Bush Fire Rubbish Heap Fire Light Pole Fire House Fire Structural Fire RTA MVF
2)	Watch	The watch on duty at the time of call	Black, Blue, Red, White
3)	Station Ground	This is different from #4 as an appliance from another station may respond to a fire in your station ground.	San Juan Station Ground
4)	Station	Station attending to the fire and completing the report.	Morvant Fire Station
5)	Date Call Received	The date the station/appliance received the call	day/month/year (only) eg. 22\04\2013
6)	Time Call Received	The time station/appliance received the call (whichever comes first). Appliance may be contacted directly by North/Fire Control. The earliest contact should be recorded.	1022 hours (Not 10:22 hrs)
7)	How call Received	Runner, telephone with number, where applicable, wireless from North/Fire Control etc.	Wireless (Fire Control)
8)	Address Given	When call was received, the address given to the sentry.	LP#22 George Lane, Belmont

		Description	Example
9)	No.....	Fire report number for the station ground in which the fire occurred. Where another appliance and crew responded the Officer is responsible for obtaining the next available fire report number from the station in which whose jurisdiction the fire occurred.	#22
10)	Wind	Thick:- Strong, Average, None	Strong, Average, None
11)	Owner's Name	Owner of the property. Where the property is owned by one person and occupied by another, both names must be stated. Where these names are not available "NOT YET ASCERTAINED" should be inserted while further enquiries are made. All efforts must be made to ascertain the names. Amendments to the report can be made at a later date. Where the property is state owned the following should be applied:- a) Uncultivated Land b) Building Where a building is Government occupied but privately owned. The owner's name must be stated in addition to "The Government of the Republic of Trinidad and Tobago, Ministry, Department"	The Government of the Republic of Trinidad and Tobago The Government of the Republic of Trinidad and Tobago, Ministry of Education, Diego Martin Central Government Secondary School. Owned by George Baynes occupied by the Government of the Republic of Trinidad and Tobago, Ministry of Finance, Financial Audit unit.
12)	Actual Address	The exact address obtained by the officer at the scene of the incident.	LP#26, APT. 2A George Lane, Belmont
13)	Distance to the nearest hydrant to fire	An approximate distance from the nearest hydrant to the property involved.	320m (approximately)

		Description	Example
	Note	All fire causes must be substantiated in the other data on the form particularly under officer's observations. Reference must be made, where applicable, to physical evidence found or fire patterns observed by the officer completing the report. Reference can also be made of interviews with witnesses that may provide creditable information to assist in cause analysis. Where this is so, efforts should be made to provide names and other details of the witness preferable in the form of a written statement.	
15)	Time Appliance left the Station	Time officer and crew reported leaving station. Where the appliance was out at the time of the call and received the information via wireless. The time the information was relayed to the appliance should be used in addition to stating that the appliance was out at the time.	1023 hours 1532 hours (appliance out)
16)	Approximate Distance to fire	The approximate distance in meters (m) from the station to the scene. Where the appliance was out at the time of the call then the approximate distance from the appliance's location to the scene should be used.	1.5 km 2.5 km
17)	Was water supply sufficient	Refers to the supply of water from fire service appliances. If additional water was required via WASA trucks or hydrants then no should be ticked.	YES ☐ NO ☐
18)	LPM Available	This is the potential rate at which the appliance can deliver water:- 1000 LPM per delivery. Each appliance has: (4 deliveries and 2 hose reels) 350 LPM per hose reels.	4000 LPM
19)	LPM Required	The actual amount of deliveries used to extinguish the fire eg. 2 deliveries and 1 hose = 2350 LPM	2000 LPM

	Description	Example
20) Type of Property Involved	A thorough description of the property containing the following:- 1) Buildings a) No of floors/storey b) Use/occupancy type eg. Dwelling c) Class of construction d) Area of property eg. (1 lot) e) Electrical connection f) Type of roof eg. Wooden framed with metal sheets. g) Type of foundation – eg. On pillars h) Size of structure i) Any other relevant information 2) Non Structural a) Area b) Items involved c) Quantity of items d) Other relevant information	Single storey dwelling of B –Class construction on one (1) lot of land. No electrical connection present. Metal framed roof covered with galvanized sheets. Structure is on 4 ft. pillars and is approximately 8 x 10m with (3) bedrooms, 1 living room, 1 kitchen, 1 washroom 4 lots of uncultivated land consisting of shrubs, bamboo and grass cleared and heaped.
Note	Be careful of using the word abandoned. The word unoccupied is a preferred legal term	An unoccupied and dilapidated house.....

	Description	Example
21)	How was fire extinguished	
	A description of firefighting operation containing the following:- - No. of lines - No. of lengths - Source of water - Pump used (if any) - Inlets used (if any) - Other fire equipment eg. Branch, fire beaters etc. - Ventilation - Isolation of power/energy sources and by whom eg. “Fire Service, T&TEC, Civilians. - Entry gained eg. “Fire Service forced entry at two (2) location” - Other relevant information.	Using 1 line, 1 length of 45mm hose passing through pump of appliance. Additionally an inlet of 1 line of 70mm hose from WASA truck TZ 1012. Forced ventilation was gained through the roof using ceiling hooks. Power lines were isolated by T&TEC crew to facilitate firefighting. Forced entry through kitchen window was necessary.
22)	Description of Damage	
	Thorough description of damage. If multiple buildings use flysheet to identify building (1) building (2) as well as multiple vehicles. This should include the following: - Damage to roof and ceiling - Damage to walls, beams, columns - Damage to floor - Damage to functional components eg. Water lines, electrical, toilets etc. - Damage to articles eg. Stove, chairs etc. - Vegetation – eg. Shrubs, bamboo etc.	Severe damage to roof and ceiling as fire was concentrated in the roof space. Minimal damage to walls and columns. Electrical and plumbing fixtures remained intact but they received severe smoke stains.
23)	Appliances	
	List of appliances attending with the station ground appliance first.	454 Water Tanker 474 Water Tanker
24)	Officers Attending	
	List of Senior Officers attending in order of seniority.	ACFO Gopaul DFO Wallen

		Description	Example
25)	FSSO and F. Sub Officer Attending	List of junior officers attending with the station ground officer first.	Fire Sub Officer Leotaud Fire Sub Station Officer Prince Fire Sub Officer Jones
26)	Number of men attending	List of Service numbers of attending Fire Officers.	#2784, #2942, #3043, #4421
27)	Total Professional	Quantity of professional Firefighters.	4
28)	Total Auxiliary	Quantity of Auxiliary Firefighters.	4
29)	Name of Casualties	Full name of casualty, age and gender in brackets eg.	John Smith (29) (M)
30)	Brief description of injuries	Simple description of injuries eg. Fatality, severe burns, fractures, flesh wound to the leg etc.	Fatality, severe burns, fractures, flesh wound to the leg etc.
31)	Treated by	Who rendered treatment eg. By standers, EHS, Fire Officers etc.	By standers, EHS, Fire Officers etc.
32)	Date	Date report is being completed.	22/05/2012
33)	Signature	Signature of Officer completing report	Fire Sub O #2498
34)	Rank	Rank of Officer completing report	
35)	Value of Building	List values if multiple buildings or property eg. Multiple cars. Give approximate value excluding value of articles. Where Insurance values are available valuing of building should consider these figures. Where other property is insured, consultation with relevant authority should be made eg. T&TEC.	Building (1) - \$ 950,000.00 Building (2) - \$ 650,000.00

Description			Example
36)	Damage of Building	Approximate value of the damage to the structure this should coincide with the description of damage in #22	Vehicle (1) - \$ 50,000.00 Vehicle (2) - \$ 6,500.00
37)	Building and stock Insured as follows	Authentic insurance figures. If documents are not available the reference must be made to the source of information.	Mr. John Seales stated that the building is insured with CLICO for 2.3 million TT dollars.
38)	Value of Stock	Value of household articles eg. Refrigerator, beds etc. if live stock is involved information of their value should be acquired. Other stock eg. Storage of lumber, cultured vegetation.	\$ 350,000.00
39)	Damage to Stock	Average figures of the damage of the stock.	\$ 50,000.00

	Description	Example
40) Officers Observations	Strictly what the Officer observes from time of arrival to departure. The following should not be included in this area: (1) Information received from witnesses (2) Actions prior to the arrival of the Fire Service. Required Information:- 1. Amount of Fire on arrival 2. Amount of smoke 3. Nature of smoke 4. Amount of by standers 5. Suspicious behaviours 6. Extent of damage on arrival 7. Development and Fire spread 8. Reaction to water 9. Time it took to extinguish fire 10. Hinderances 11. Assistance rendered 12. Evidence discovered 13. Other relevant information of that nature	(Colour, density) An arrival building was well alight, with theme issuing from the kitchen window. Thick heavy black smoke was seen coming from the living room door and windows. Several persons were attempting to extinguish the fire using a bucket brigade. On entry fire had already ravaged the kitchen and living room, no fire was observed in the bedroom at that time.
Note	If additional space is required a fly sheet can be used and certify with the following information • Appendix No. 1,2,3 etc. • Address of Fire • Date of Fire • Fire Report Number • Date of Report • Signature of Officer • Counter signed by FSO	There was a strong smell of a substance similar to the smell of kerosene, particularly in the living room area. Three persons reported to be the occupants of the house were attempting to salvage items from the bedroom area. Sudden spread of the fire occurred when there was an explosion in the kitchen. This sudden spread occurred through the roof space. T&TEC crew under the supervision of Jake Tony isolated the electrical supply.

CONCLUSION

Efforts should be made to avoid major alterations of the form. As far as is practicable information should be added to give explanation of findings, assumptions etc.

Officers are required to ensure all forty (40) areas of the form are thoroughly completed before they are submitted to Fire Prevention.

If unsure Officers are asked to clarify any matter or concern with the Fire Prevention Section at 625 – 2671 – 5 Ext. 2322 or 2323.