

				limit deviation value							rat	tif			Stage marking		qua	weight	scale	figure numbe	JXHSV05P-02005-d
edi tio n	tab	Change the content	date	Straight degree peace The surface degree is not noted Toleran ce value	0.05	> 10~30 0.1	> 30~100	> 100~300 0.4	> 300~100 0 0.6	> 1000~30 00 0.8	y		1, the	1		urking	1	0.0	1:1	nam e	AB shaft mounting plate 1