

editio	A0
n	
	20019900845
code	2





technical requirement:

- To deburr, the sharp angle is too blunt;
 No note of the chamfer C0.2;
 Drawing for all hole position tolerance dimensions ± 0.1mm;
 Reference to 3D drawing for unannotated dimension;
 The surface to prevent scraping, bumping, crushing, deformation and other bad.

			linear tol 84-K	erance is	GB / T180)4-m; the sl	nape tolerar	nce is GB /	desi gn	Wang Enda	2024/3/12	Jie	Xinhua Technology	materi al	SUS304
		Linear basic ruler, pole of inch	> 6~ 30		> 120~ 400	1	> 1000~ 2000	2> 22000~4 000	examin e and			Co.	., LTD	type	SV05P
		section, limit	±0.2	±0.3	±0.5	±0.8	±1.2	±2	verify			<u> </u>	<u> </u>		W/161/05B 00000

				deviation value									marki	ng	ty			numbe	
edi tio n	tab	Change the content	date	Straight degree peace The surface degree is not noted Toleran ce value	0.05	I	>100~ 300 0.4	> 300~ 1000 0.6	>1000~ 3000 0.8	70	1, the	1			1	0.0	4:1	r name	idler shaft