


DC-DC Converter 3MHz, 600mA Step-Down



Vmin	2.7	>	
Vmax	5.5	V	
Source	600	mA	
peak l	1200	mA	

Vout=Vfb\*(1+R1/R2)

Vout can be ajdused with different values of R1 and R2

Step Down				
www.threemode.com				
Size	Email		Rev	
A4	threemode3@gm			
Design	by 3Mode Team			
Drawn b	by 3Mode Team	Sheet 1		