


ZZ1 ■ Install label in silkscreened box after final wash. Text shall be 8 pt font. Text shall be per the Label Table in the PDF schematic.

222 ■ These assemblies are ESD sensitive. ESD precautions shall be observed.

ZZZ ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.


ZZ4 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.

These assemblies must comply with workmanship standards IPC-T-1950 Class 2, unless otherwise specified.



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.
ASSEMBLY VARIANT: 002

PCB VIEWED FROM TOP SIDE	BOARD #: PROC051	REV: C	SVN REV: Not In VersionControl
LAYER NAME = M5 Assembly Top	TID #: N/A		
PLOT NAME = Top Assembly Drawing	GENERATED : 3/12/2019 10:59:15 AM		TEXAS INSTRUMENTS



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.
ASSEMBLY VARIANT: 002

PCB VIEWED FROM BOTTOM SIDE	BOARD #: PROC051	REV: C	SVN REV: Not In VersionControl
LAYER NAME = M6 Assembly Bottom	TID #: N/A		
PLOT NAME = Bottom Assembly Drawing	GENERATED : 3/12/2019 10:59:18 AM		TEXAS INSTRUMENTS