PART NAME	PART IMAGE	# REQUIRED PER ROBOT
TO-220	3	20
TO-127		27
ANDERSON POWER POLE		50
RH-25		7
RH-50	MANAGE TO S	1
PACIFIC RESISTORS		13
BOURNS 3255/3250	Bourns Model 3250	15
BOURNS TRIMPOTS	BOURNS	36
BOURNS 3292		6
TRANSISTOR TO-92		14
CAPICITORS		15
14 PIN DIP IC		9
8 PIN DIP IC	[613]	7
PLAYBACK HEAD		3
PLAYBACK HEAD		7
10 PIN ISO PACK	N/A	10
8 PIN ISO PACK	N/A	2
UNKNOWN 1	0.0	6

UNKNOWN 2		2
UNKNOWN 3		5
UNKNOWN 4		4
UNKNOWN 5	E CE	2
UNKNOWN 6		11
UNKNOWN 7		1
UNKNOWN 8		1
UNKNOWN 9		2
TOTAL		276