Configurations with Magnotometers, Sun Sensors and Earth Sensors In the figures on the left all have the boom for the Ε magnetimetter Ε undeployed. Below are figures with the boom deployed. G Α Ι 4 Reaction wheels & Isometric X-ray
2 Magnetic Tourquers frount view 4 Momentum Wheels & 2 Magnetic torquers Ε Ε Isometric X-ray back View Detail View: I Н G 9 Ι 4 Magnetic Torquers 6 Thursters