


The degradation law drives the spread; plant parameters add nothing



Simulation: 30 units, one dispersion axis switched on at a time, all others canonical; values below 10^{-9} shown as ≈ 0 .