



Fire Protection Inspection Report

Property Information

THE STANTON

2089 WEST 43RD AVENUE
VANCOUVER, V6M 2B7

Inspection Date:

January 15, 2025

Earth Wind and Fire

Fire Protection Services
604-299-1030 | info@ewf.ca



Date of Service: 1/15/2025		Work Order Number: #0313-2025	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

Table of Contents

- ☐ Fire Alarm System
- ☐ Common Area Devices
- ☐ In-suite Devices
- ☐ Sprinkler System
- ☐ Fire Extinguishers
- ☐ Emergency Lighting
- ☐ Hydrant
- ☐ Winterization
- ☐ Generator (Electrical Power Supply)
- ☐ Backflow
- ☐ Monitoring
- ☐ Smoke Control
- ☐ Suppression Systems
- ☐ Standpipe
- ☐ Kitchen



Date of Service: 1/15/2025		Work Order Number: #0313-2025ANNUAL	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

Executive Summary

Inspection Types Completed

- Fire Alarm System
- Common Area Devices
- Fire Extinguishers
- Emergency Lighting

Deficiency Summary

Severity	Count	Status
Critical	0	None
Major	0	None
Minor	0	None
Total Deficiencies	0	

Overall Inspection Status

DEFICIENT - Action Required



Date of Service: 1/15/2025	Work Order Number: #0313-2025ANNUAL		
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

INSPECTION, TESTING, AND MAINTENANCE OF FIRE ALARM SYSTEMS

Systems Provides: ☐ Single Stage Operation ☒ Two Stage Operation	EDWARDS EST 3X
The fire alarm system is connected to a fire signal receiving centre.	☐ Yes ☐ No
Name, if applicable: BARTEC	

The entire fire alarm system has been inspected and tested in accordance with CAN/ULC-S536:2019, Inspection and Testing of Fire Alarm Systems.	☒ Yes	☐ No
The fire alarm system is fully functional.	☐ Yes	☒ No
During the Annual Inspection and Test were any Deficiencies Identified? See Page 2, if applicable.	☐ Yes	☐ No
As of the following Date (M/D/Y) all identified Deficiencies have been corrected:	☐ Yes	☐ No
During the Annual Inspection and Test were any Recommendations Identified? See Page 3, if applicable	☐ Yes	☐ No

The information in this report, which comprises 11 pages, affirms that the equipment listed here-in was tested and inspected in conformance with ULC 536:2019 (2024); Standard for Inspection and Testing of Fire Alarm Systems, applicable codes, bylaws, Standards, and the manufacturer's requirements by a qualified technician. The equipment was left in an operational condition except as noted above.

Supervising / Primary Technician Name	Certification Number / Seal	Date	Signature
Lester Abril	FIRE PROTECTION ASTTBC LESTER ABRIL 1448	2025-01-15	Earth Wind and Fire
Technician Conducting Test and Inspection	Certification Number / Seal	Date	Signature
Alexander Smith	FIRE PROTECTION ASTTBC ALEXANDER SMITH 1449	2025-01-15	Earth Wind and Fire

Company Conducting Test: Earth Wind and Fire	Company Phone Number: 604-299-1030
---	---



Date of Service: 1/15/2025		Work Order Number: #0313-2025ANNUAL	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

INSPECTION, TESTING, AND MAINTENANCE OF FIRE ALARM SYSTEMS

22.1 Control Unit or Transponder Inspection

Control unit or transponder location: LOBBY
Control unit or transponder identification: EDWARDS EST 3X

		Yes	No	N/A
A	Input circuit designations correctly identified in relation to connected field devices.	☒	☐	☐
B	Output circuit designations correctly identified in relation to connected field devices.	☒	☐	☐
C	Correct designations for common control functions and indicators.	☒	☐	☐
D	Plug-in components and modules securely in place.	☒	☐	☐
E	Plug-in cables securely in place.	☒	☐	☐
F	Record the date, revision and version of firmware and software program.	☒	☐	☐
G	Clean and free of dust and dirt.	☒	☐	☐
H	Fuses in accordance with manufacturer's specification	☒	☐	☐
I	Control unit or transponder lock functional	☒	☐	☐
J	Termination points from wiring to field devices secure	☒	☐	☐

RESULT	PASS
COMMENTS	



Date of Service: 1/15/2025		Work Order Number: #0313-2025ANNUAL	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

INSPECTION, TESTING, AND MAINTENANCE OF FIRE ALARM SYSTEMS

22.2 Control Unit or Transponder Test

Control unit or transponder location: LOBBY				
Control unit or transponder identification: EDWARDS EST 3X				
		Yes	No	N/A
A	Power 'ON' visual indicator operates.	☒	☐	☐
B	Time and date indication corresponds with local time and date.	☒	☐	☐
C	Common visual trouble signal operates.	☒	☐	☐
D	Common audible trouble signal operates.	☒	☐	☐
E	Trouble signal silence switch operates.	☒	☐	☐
F	Main power supply failure trouble signal operates.	☒	☐	☐
G	Trouble signal operates during positive and negative ground fault tests	☒	☐	☐
H	Alert signal operates.	☐	☐	☒
I	Alarm signal operates.	☒	☐	☐
J	Automatic transfer from alert signal to alarm signal operates.	☐	☐	☒
K	Manual transfer from alert signal to alarm signal operates.	☐	☐	☒
L	Automatic transfer from alert signal to alarm signal cancel (acknowledge) feature operates on a two-stage system.	☐	☐	☒
M	Alarm signal silence inhibit function operates.	☒	☐	☐
N	Alarm signal manual silence operates.	☒	☐	☐
O	Alarm signal silence visual indication operates.	☒	☐	☐
P	Alarm signals when silenced, automatically reinitiate only upon subsequent alarm from another NBC required fire alarm zone.	☒	☐	☐
Q	Duration of alarm signal prior to automatic silence.	☐	☐	☒



Date of Service: 1/15/2025		Work Order Number: #0313-2025ANNUAL	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

R	Audible and visual alert signals and alarm signals programmed and operate as per design and specification, or documentation as provided in Section 21.	☐	☐	☐
S	Input circuit, alarm and supervisory operation, including audible and visual indication operates.	☐	☐	☐
T	Input circuit supervision fault causes a trouble indication.	☐	☐	☐
U	Output circuit alarm indicators operate.	☐	☐	☐
V	Output circuit supervision fault causes a trouble indication.	☐	☐	☐
W	Visual indicator test (lamp test) operates.	☐	☐	☐
X	Coded signal sequences operate not less than the required number of times and the correct signal operates thereafter.	☐	☐	☐
Y	Coded signal sequences are not interrupted by subsequent alarms.	☐	☐	☐
Z	Ancillary device by-pass results in a trouble signal.	☐	☐	☐
AA	Input circuit to output circuit operation, including ancillary device circuits, for correct program operation, as per design and specification, or documentation as detailed in D, Description of Fire Alarm System for Inspection and Test Procedures.	☐	☐	☐
BB	System Reset operates.	☐	☐	☐
CC	Main power supply to emergency power supply operates	☐	☐	☐
DD	Smoke detector alarm verification (status change confirmation) verified (Refer to 14.4.3, Smoke Detector Alarm Verification (Status Change Confirmation)	☐	☐	☐

RESULT	DEFICIENT
COMMENTS	CRU BUZZERS DIDN'T WORK TROUBLE SHOOTING REQUIRED



Date of Service: 1/15/2025		Work Order Number: #0313-2025ANNUAL	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

INSPECTION, TESTING, AND MAINTENANCE OF FIRE ALARM SYSTEMS

22.4 Power Supply Inspection

Control unit or transponder location: LOBBY
Control unit or transponder identification: EDWARDS EST 3X

		Yes	No	N/A
A	Fused in accordance with the manufacturer's marked rating of the system.	☒	☐	☐
B	The primary supply is equipped with the identified disconnect means.	☒	☐	☐
C	Adequate to meet the requirements of the system.	☒	☐	☐
D	A short on the isolated side of each power isolation module results in a trouble condition	☐	☐	☒
E	Operation of a device on the source side of each shorted power isolation module is confirmed	☐	☐	☒
F	Power for ancillary devices is taken from a source separate from the fire alarm system control unit or transponder power supply	☐	☐	☒
G	Power for ancillary devices is taken from the control unit or transponder that is designed to provide such power.	☐	☐	☒
H	Ancillary devices, which are powered from control unit or transponder, are recorded.	☐	☐	☒

RESULT	PASS
COMMENTS	Circuit disconnect location: P1 ELECTRICAL RM, ID: #24



Date of Service: 1/15/2025		Work Order Number: #0313-2025	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

INSPECTION, TESTING, AND MAINTENANCE OF FIRE ALARM SYSTEMS

22.5 Emergency Power Supply Test and Inspection

Control unit or transponder location: LOBBY
Control unit or transponder identification: EDWARDS

		Yes	No	N/A
A	Correct battery type as recommended by manufacturer.	☒	☐	☐
B	Correct battery rating as determined by battery calculations based on full system load.	☒	☐	☐
C	Battery voltage with main power supply 'ON'. Voltage: 27.33 V dc, Current: 0.15 A	☒	☐	☐
D	Battery voltage and current with main power supply 'OFF' and fire alarm system in supervisory condition. Voltage: 25.62 V dc, Current: 0.39 A	☒	☐	☐
E	Battery voltage and current with main power supply 'OFF' and fire alarm system in full load alarm condition. Voltage: 24.775 V dc, Current: 4.71 A	☒	☐	☐
F	Battery free of physical damage.	☒	☐	☐
G	Battery terminals cleaned and lubricated.	☒	☐	☐
H	Battery terminals clamped tightly.	☒	☐	☐
I	Correct electrolyte level.	☐	☐	☒
J	Specific gravity of electrolyte is within manufacturer's specifications.	☐	☐	☒
K	Battery free of Electrolyte leakage.	☐	☐	☒
L	Adequately ventilated.	☐	☐	☒
M	Battery manufacturer's date code.	☒	☐	☐
N	Disconnection of battery causes trouble signal at the fire alarm control unit.	☒	☐	☐
O	Indicate type of battery tests performed.	☒	☐	☐
P	Record calculated battery capacity (Refer to Annex C2)	☒	☐	☐
Q	Record battery terminal voltage after completion of tests	☒	☐	☐



Date of Service: 1/15/2025		Work Order Number: #0313-2025	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

R	Confirm battery voltage not less than 85% of its rating after the tests.	☐	☐	☐
----------	--	--------------------------	--------------------------	--------------------------

RESULT	PASS
COMMENTS	



Date of Service: 1/15/2025		Work Order Number: #0313-2025ANNUAL	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

INSPECTION, TESTING, AND MAINTENANCE OF FIRE ALARM SYSTEMS

22.6 Annunciator, Remote Trouble Signal Unit, Display and Control Centre Test and Inspection

Control unit or transponder location: LOBBY
Control unit or transponder identification: EDWARDS

		Yes	No	N/A
A	Power 'on' indicator operates.	☐	☐	☐
B	Individual alarm and supervisory zone designation labels are properly identified.	☒	☐	☐
C	Where individual devices are annunciated confirm the individual alarm and supervisory indications are properly identified	☐	☒	☐
D	Where active and supporting field devices are utilized, the device location is programmed using label/descriptor shall be confirmed.	☒	☐	☐
E	Common trouble signal operates.	☒	☐	☐
F	Visual indicator test (lamp test) operates.	☒	☐	☐
G	Input wiring from control unit or transponder is supervised.	☒	☐	☐
H	Alarm signal silence visual indicator operates.	☒	☐	☐
I	Switches for ancillary functions operate as per design and specification, or in accordance with documentation as detailed in Annex D, Description of Fire Alarm System for Inspection and Test Procedures.	☒	☐	☐
J	Other ancillary function visual indicators operate.	☒	☐	☐
K	Manual activation of alarm signal and indication operates.	☒	☐	☐
L	Displays are visible in installed location.	☒	☐	☐
M	Operates on emergency power.	☒	☐	☐

RESULT	DEFICIENT
COMMENTS	CRU DEVICES NOT LISTED IN THE LED ANNUNCIATOR



Date of Service: 1/15/2025		Work Order Number: #0313-2025	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

Fire Alarm Devices

Location	Type	Result	Notes
LOBBY	Smoke Detector	PASS	
MECHANICAL ROOM	Heat Detector	PASS	
STAIRWELL A	Pull Station	PASS	
CORRIDOR 1	Horn/Strobe	DEFICIENT	Strobe not flashing



Date of Service: 1/15/2025		Work Order Number: #0313-2025	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

Fire Extinguishers

Location	Type	Serial Number	Result
LOBBY	10lb ABC	FE-001	PASS
KITCHEN	5lb BC	FE-002	PASS



Date of Service: 1/15/2025		Work Order Number: #0313-2025	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

Emergency Lighting

Location	Functional Test	Duration Test	Comments
STAIRWELL A	PASS	N/A	
EXIT DOOR 1	FAIL	N/A	Battery depleted



Date of Service: 1/15/2025		Work Order Number: #0313-2025ANNUAL	
☐ Daily	☐ Weekly	☐ Monthly	☐ Quarterly
☒ Annual	☐ 3 Year	☐ 5 Year	☐ 25 Year
Contact Person: John Smith		Phone: 778-320-2245	

Building Name: THE STANTON	PM or Owner: Property Management Inc	Phone: 604-555-1234
Address: 2089 WEST 43RD AVENUE		
City: VANCOUVER	Postal Code: V6M 2B7	

Deficiencies Summary

System	Location	Description
Fire Alarm System	CORRIDOR 1	Horn/Strobe device not functioning properly - strobe not flashing during alarm test
Emergency Lighting	EXIT DOOR 1	Emergency light failed functional test - battery appears depleted and requires replacement

