

## **AVR Binary Reversing**

mongii@grayhash

### 개요

• AVR의 소스코드가 없을 때, 바이너리를 리버싱 하는 방법 설명

• AVR 어셈블리어 학습 방법 설명

• AVR 바이너리의 구조 이해


## AVR용 gdb의 위치

→ 컴퓨터 →	도달 니으크 (C.) ▶ Program Files (X86	i) ▶ Atmel ▶ Atmel Toolchain ▶ AVF	no GCC ▶ Native ▶ 3.4	+.1030 • avi8-gnu-toolchain • bin
▼ 라이브러리에 포	도함 ▼ 공유 대상 ▼ 새 폴더			
즐겨찿기	이를	수정한 날짜 유형	형 크기	
다운로드	avr-addr2line.exe	2014-04-30 오후 응용	용 프로그램 4	435KB
바탕 화면	avr-ar.exe	2014-04-30 오후 응용	용 프로그램 4	454KB
최근 위치	avr-as.exe	2014-04-30 오후 응용	용 프로그램 (	600KB
	avr-c++.exe	2014-04-30 오후 응용	용 프로그램 5	587KB
라이브러리	avr-c++filt.exe	2014-04-30 오후 응용	용 프로그램 4	434KB
문서	avr-cpp.exe	2014-04-30 오후 응용	용 프로그램 5	586KB
비디오	avr-elfedit.exe	2014-04-30 오후 응용	용 프로그램	55KB
사진	avr-g++.exe	2014-04-30 오후 응용	용 프로그램 5	587KB
음악	avr-gcc.exe	2014-04-30 오후 응용	용 프로그램 5	585KB
	avr-gcc-4.8.1.exe	2014-04-30 오후 응용	용 프로그램 5	585KB
컴퓨터	avr-gcc-ar.exe	2014-04-30 오후 응용	· 프로그램	50KB
로컬 디스크 (C:)	avr-gcc-nm.exe	2014-04-30 오후 응용	· 프로그램	50KB
) 시스템 예약 (D:)	avr-gcc-ranlib.exe	2014-04-30 오후 응용	용 프로그램	50KB
) 업무 하드 (F:)	avr-gcov.exe	2014-04-30 오후 응용	용 프로그램 2	231KB
2TB VMWARE (G:)	avr-gdb.exe	2014-04-30 오후 응용	용 프로그램 3,6	695KB
	avr-gprof.exe	2014-04-30 오후 응용	용 프로그램 4	487KB
네트워크	avr-ld.bfd.exe	2014-04-30 오후 응용	용 프로그램 8	864KB
	avr-ld.exe	2014-04-30 오후 응용	용 프로그램 8	864KB
	avr-man	2014-04-30 오후 파일	빌	2KB
	avr-nm.exe	2014-04-30 오후 응용	용 프로그램 4	443KB
	avr-objcopy.exe	2014-04-30 오후 응용	용 프로그램 5	564KB
	avr-objdump.exe	2014-04-30 오후 응용	용 프로그램 (	654KB
	avr-ranlib.exe	2014-04-30 오후 응용	용 프로그램 4	454KB
	avr-readelf.exe	2014-04-30 오후 응용	용 프로그램 3	340KB
	avr-size.exe	2014-04-30 오후 응용	용 프로그램 4	444KB
	avr-strings.exe	2014-04-30 오후 응용	용 프로그램 4	436KB
	avr-strip.exe	2014-04-30 오후 응용	용 프로그램 5	564KB
	⊗ libtermcap-0.dll	2014-04-30 오후 응용	용 프로그램 확장	9KB
	mingwm10.dll	2014-04-30 오후 응용	용 프로그램 확장	9KB


### cmd 실행

⊿vr-addr2line.exe	2014-04-30 오후	응용 프로그램	435KB
avr-ar.exe	2014-04-30 오후	응용 프로그램	454KB
avr-as.exe	2014-04-30 오후	응용 프로그램	600KB
avr-c++.exe	2014-04-30 오후	응용 프로그램	587KB
avr-c++filt.exe	2014-04-30 오후	응용 프로그램	434KB
avr-cpp.exe	2014-04-30 오후	응용 프로그램	586KB
avr-elfedit.exe	2014-04-30 오후	응용 프로그램	55KB
avr-g++.exe	2014-04-30 오후	응용 프로그램	587KB
avr-gcc.exe	2014-04-30 오후	응용 프로그램	585KB
avr-gcc-4.8.1.exe	2014-04-30 오후	응용 프로그램	585KB
avr-gcc-ar.exe	2014-04-30 오후	응용 프로그램	50KB
avr-gcc-nm.exe	2014-04-30 오후	응용 프로그램	50KB
avr-gcc-ranlib.exe	2014-04-30 오후	응용 프로그램	50KB
avr-gcov.exe	2014-04-30 오후	응용 프로그램	231KB
avr-gdb.exe	2014-04-30 오후	응용 프로그램	3,695KB
avr-gprof.exe	2014-04-30 오후	응용 프로그램	487KB
avr-ld.bfd.exe	2014-04-30 오후	응용 프로그램	864KB
avr-ld.exe	2014-04-30 오후	응용 프로그램	864KB
avr-man	2014-04-30 오후	파일	2KB
avr-nm.exe	2014-04-30 오후	응용 프로그램	443KB
avr-objcopy.exe	2014-04-30 오후	응용 프로그램	564KB
avr-objdump.exe	2014-04-30 오후	응용 프로그램	654KB
avr-ranlib.exe	2014-04-30 오후	응용 프로그램	454KB
avr-readelf.exe	2014-04-30 오후	응용 프로그램	340KB
avr-size.exe	2014-04-30 오후	응용 프로그램	444KB
avr-strings.exe	2014-04-30 오후	응용 프로그램	436KB
avr-strip.exe	2014-04-30 오후	응용 프로그램	564KB
LED_BLANK.elf	2015-02-21 오후	ELF 파일	5KB
libtermcap-0.dll	2014-04-30 오후	응용 프로그램 확장	9KB
Mingwm10.dll	2014-04-30 오후	응용 프로그램 확장	9KB

#### Shift+마우스 우클릭



### gdb 실행




### 디버깅 대상 코드


```
#define F_CPU 800000UL
#include <avr/io.h>
#include <util/delay.h>
int main(void)
{
  DDRA = 0xff;
  while(1)
     PORTA = 0xff;
    _delay_ms(1000);
     PORTA = 0x00;
    _delay_ms(1000);
```

### 컴파일 된 바이너리의 위치

• gdb가 있는 폴더로 복사



### 대상 바이너리 Open



### 주요 명령어


- file: 디버깅 대상 파일 열기
- disassemble : 디스어셈블링
- x/10i [주소]: 10개의 명령어 출력

- run : 실행
- break : 브레이크 포인트 설정
- continue : 실행 재개

```
aig symbols from LED_BLANK.elf...done.
 db) disass main
Dump of assembler code for function main:
   0x0000009e <+0>:
                         1di
                                 r24, 0xFF
                                                   ; 255
                                 0x1a, r24
   0x0000000a0 <+2>:
                                                   ; 26
                         out
                                                   ; 27
   0x0000000a2 <+4>:
                         out
                                 0x1b. r24
   0x0000000a4 <+6>:
                         ldi
                                 r18, ØxFF
                                                   ; 255
   0x0000000a6 <+8>:
                         ldi
                                 r19, 0x69
                                                   : 105
   0x0000000a8 <+10>:
                                                   ; 24
                         ldi
                                 r25, 0x18
                                 r18, 0x01
   0x0000000aa <+12>:
                                                   ; 1
                         subi
   0x0000000ac <+14>:
                         sbci
                                 r19, 0x00
                                                   : 0
                                 r25, 0x00
                                                   ; 0
   0x0000000ae <+16>:
                         sbci
   0х0000000ь0 <+18>:
                                 . –8
                                                     0xaa <main+12>
                         brne
                                                     0xb4 <main+22>
   0x0000000b2 <+20>:
                         rjmp
                                  . +0
   0x0000000b4 <+22>:
                         nop
   0x000000b6 <+24>:
                                 0x1b, r1
                                                   ; 27
                         out
   0x000000b8 <+26>:
                                 r18, ØxFF
                                                   : 255
                         ldi
                                                   : 105
   0x0000000ba <+28>:
                         ldi
                                 r19, 0x69
   0x000000bc <+30>:
                                                   ; 24
                         ldi
                                 r25, 0x18
   0x0000000be <+32>:
                         subi
                                 r18, 0x01
                                                   ; 1
                                                  ; 0
   0x000000c0 <+34>:
                         sbci
                                 r19, 0x00
   0x000000c2 <+36>:
                                                  ; 0
                         sbci
                                 r25, 0x00
   0x000000c4 <+38>:
                         brne
                                  . –8
                                                     Oxbe <main+32>
                                                     0xc8 <main+42>
   0x000000c6 <+40>:
                         rjmp
                                  . +0
   0x000000c8 <+42>:
                         nop
                                                  ; 0xa2 <main+4>
   0x000000ca <+44>:
                         rjmp
                                  .-42
End of assembler dump.
(gdb)
```

### AVR의 레지스터

- 32개의 8비트 범용 레지스터
  - R0~R31
- X, Y, Z 레지스터
  - 사실상 R26~R31 레지스터
  - 16비트 크기로 사용 가능 ex> Y 레지스터 == 스택 포인터



```
(gdb) disass main
Dump of assembler code for function main:
   0x0000009e <+0>:
                        ldi
                                r24, 0xFF
                                                  ; 255
  0x000000a0 <+2>:
                                 0x1a, r24
                                                  ; 26
                        out
  0x000000a2 <+4>:
                                 0x1b, r24
                                                  ; 27
                        out
  0x000000a4 <+6>:
                        ldi
                                r18, 0xFF
                                                  ; 255
  0x000000a6 <+8>:
                                                  ; 105
                        ldi
                                r19, 0x69
  0x000000a8 <+10>:
                        ldi
                                r25, 0x18
                                                  ; 24
  0x000000aa <+12>:
                                 r18, 0x01
                                                  ; 1
                        subi
  0x000000ac <+14>:
                        sbci
                                 r19, 0x00
                                                   0
  0x000000ae <+16>:
                        sbci
                                 r25, 0x00
                                                   0
  0x000000b0 <+18>:
                        brne
                                 .-8
                                                    0xaa <main+12>
  0x000000b2 <+20>:
                                                    0xb4 <main+22>
                        rjmp
                                 .+0
  0x000000b4 <+22>:
                        nop
  0x000000b6 <+24>:
                                 0x1b, r1
                                                  ; 27
                        out
  0x000000b8 <+26>:
                        ldi
                                r18, 0xFF
                                                  ; 255
  0x000000ba <+28>:
                        ldi
                                 r19, 0x69
                                                  : 105
  0x000000bc <+30>:
                        ldi
                                 r25, 0x18
                                                  ; 24
  0x000000be <+32>:
                                 r18, 0x01
                                                  ; 1
                        subi
  0x000000c0 <+34>:
                        sbci
                                 r19, 0x00
                                                   0
  0x000000c2 < +36>:
                        sbci
                                 r25, 0x00
                                                 ; 0
  0x000000c4 < +38>:
                                 .-8
                                                    0xbe <main+32>
                        brne
  0x000000c6 <+40>:
                                 .+0
                                                    0xc8 <main+42>
                        rjmp
  0x000000c8 <+42>:
                        nop
  0x000000ca <+44>:
                                 .-42
                                                 ; 0xa2 <main+4>
                        rjmp
End of assembler dump.
(gdb)
```

### Instruction set summary

#### Datasheet 352p~355p

#### ປ. Instruction Set Summary

Mnemonics	Operands	Description	Operation	Flags	#Clock
ARITHMETIC AND	LOGIC INSTRUCTION	ONS	·	<u>'</u>	
ADD	Rd, Rr	Add two Registers	Rd ← Rd + Rr	Z,C,N,V,H	1
ADC	Rd, Rr	Add with Carry two Registers	$Rd \leftarrow Rd + Rr + C$	Z,C,N,V,H	1
ADIW	RdI,K	Add Immediate to Word	Rdh:Rdl ← Rdh:Rdl + K	Z,C,N,V,S	2
SUB	Rd, Rr	Subtract two Registers	Rd ← Rd - Rr	Z,C,N,V,H	1
SUBI	Rd, K	Subtract Constant from Register	Rd ← Rd - K	Z,C,N,V,H	1
SBC	Rd, Rr	Subtract with Carry two Registers	$Rd \leftarrow Rd - Rr - C$	Z,C,N,V,H	1
SBCI	Rd, K	Subtract with Carry Constant from Reg.	Rd ← Rd - K - C	Z,C,N,V,H	1
SBIW	RdI,K	Subtract Immediate from Word	Rdh:Rdl ← Rdh:Rdl - K	Z,C,N,V,S	2
AND	Rd, Rr	Logical AND Registers	$Rd \leftarrow Rd \bullet Rr$	Z,N,V	1
ANDI	Rd, K	Logical AND Register and Constant	$Rd \leftarrow Rd \bullet K$	Z,N,V	1
OR	Rd, Rr	Logical OR Registers	Rd ← Rd v Rr	Z,N,V	1
ORI	Rd, K	Logical OR Register and Constant	$Rd \leftarrow Rd \vee K$	Z,N,V	1
EOR	Rd, Rr	Exclusive OR Registers	$Rd \leftarrow Rd \oplus Rr$	Z,N,V	1
COM	Rd	One's Complement	Rd ← \$FF – Rd	Z,C,N,V	1
NEG	Rd	Two's Complement	Rd ← \$00 – Rd	Z,C,N,V,H	1
SBR	Rd,K	Set Bit(s) in Register	$Rd \leftarrow Rd \vee K$	Z,N,V	1
CBR	Rd,K	Clear Bit(s) in Register	$Rd \leftarrow Rd \bullet (\$FF - K)$	Z,N,V	1
INC	Rd	Increment	Rd ← Rd + 1	Z,N,V	1
DEC	Rd	Decrement	Rd ← Rd – 1	Z,N,V	1
TST	Rd	Test for Zero or Minus	$Rd \leftarrow Rd \bullet Rd$	Z,N,V	1
CLR	Rd	Clear Register	$Rd \leftarrow Rd \oplus Rd$	Z,N,V	1
SER	Rd	Set Register	Rd ← \$FF	None	1
MUL	Rd, Rr	Multiply Unsigned	$R1:R0 \leftarrow Rd \times Rr$	Z,C	2
MULS	Rd, Rr	Multiply Signed	R1:R0 ← Rd x Rr	Z,C	2
MULSU	Rd, Rr	Multiply Signed with Unsigned	$R1:R0 \leftarrow Rd \times Rr$	Z,C	2
FMUL	Rd, Rr	Fractional Multiply Unsigned	$R1:R0 \leftarrow (Rd \times Rr) << 1$	Z,C	2
FMULS	Rd, Rr	Fractional Multiply Signed	R1:R0 ← (Rd x Rr) << 1	Z,C	2
FMULSU	Rd, Rr	Fractional Multiply Signed with Unsigned	$R1:R0 \leftarrow (Rd \times Rr) << 1$	Z,C	2
BRANCH INSTRU	CTIONS				
RJMP	k	Relative Jump	PC ← PC + k + 1	None	2
IJMP		Indirect Jump to (Z)	PC ← Z	None	2
JMP	k	Direct Jump	PC ← k	None	3
RCALL	k	Relative Subroutine Call	PC ← PC + k + 1	None	3
ICALL		Indirect Call to (Z)	PC ← Z	None	3
CALL	k	Direct Subroutine Call	PC ← k	None	4
RET		Subroutine Return	PC ← STACK	None	4
RETI		Interrupt Return	PC ← STACK	1	4
CPSE	Rd,Rr	Compare, Skip if Equal	if (Rd = Rr) PC ← PC + 2 or 3	None	1/2/
CP	Rd,Rr	Compare	Rd – Rr	Z, N,V,C,H	

### Main 함수 내의 명령어들

- LDI: Load Immediate value
- OUT : Out Port
- SUBI: Subtract Constant from Register
- SBCI: Subtract with Carry Constant from Reg
- BRNE: Branch if Not Equal
- RJMP: Relative Jump
- NOP: No Operation

#### Subtract with Carry Constant from Reg

• Carry가 발생하는 경우 1 0b11111111 + 0b00000001 => 0b00000000 with carry flag on

• Carry가 발생하는 경우 2 0b00000000 - 0b00000001 => 0b11111111 with carry flag on

#### Subtract with Carry Constant from Reg

SBCI r0, 10
 -r0 = 20 / carry flag = 1

Subtract with carry

$$-r0(20) - 10 - 1 => 9$$

```
(gdb) disass main
Dump of assembler code for function main:
   0x0000009e <+0>:
                        ldi
                                r24, 0xFF
  0x000000a0 <+2>:
                                0x1a, r24
                        out
  0x000000a2 <+4>:
                                0x1b, r24
                        out
  0x000000a4 <+6>:
                        ldi
                                r18, 0xFF
  0x000000a6 <+8>:
                        ldi
                                r19, 0x69
  0x000000a8 <+10>:
                        ldi
                                r25, 0x18
  0x000000aa <+12>:
                        subi
                                r18, 0x01
  0x000000ac <+14>:
                        sbci
                                r19, 0x00
  0x000000ae <+16>:
                        sbci
                                r25, 0x00
  0x000000b0 <+18>:
                        brne
                                 .-8
  0x000000b2 <+20>:
                        rjmp
                                 .+0
                                                 ; main+22로 jump
  0x000000b4 <+22>:
                        nop
  0x000000b6 <+24>:
                                0x1b, r1
                                                 ; 0x1b 포트에 r1을
                        out
  0x000000b8 <+26>:
                        ldi
                                r18, 0xFF
  0x000000ba <+28>:
                        ldi
                                r19, 0x69
                        ldi
  0x000000bc <+30>:
                                r25, 0x18
  0x000000be <+32>:
                        subi
                                r18, 0x01
  0x000000c0 <+34>:
                        sbci
                                r19, 0x00
  0x000000c2 <+36>:
                        sbci
                                r25, 0x00
  0x000000c4 <+38>:
                        brne
                                 .-8
  0x000000c6 <+40>:
                                 .+0
                        rjmp
  0x000000c8 <+42>:
                        nop
  0x000000ca <+44>:
                        rjmp
                                 .-42
End of assembler dump.
(gdb)
```

```
(gdb) disass main
Dump of assembler code for function main:
  0x0000009e <+0>:
                        ldi
                                r24, 0xFF
                                                                                     DDRA=0xFF
  0x000000a0 <+2>:
                                0x1a, r24
                        out
  0x000000a2 <+4>:
                                0x1b, r24
                        out
  0x000000a4 <+6>:
                        ldi
                                r18, 0xFF
  0x000000a6 <+8>:
                        ldi
                                r19, 0x69
  0x000000a8 <+10>:
                        ldi
                                r25, 0x18
  0x000000aa <+12>:
                        subi
                                r18, 0x01
  0x000000ac <+14>:
                        sbci
                                r19, 0x00
  0x000000ae <+16>:
                        sbci
                                r25, 0x00
  0x000000b0 <+18>:
                        brne
                                .-8
  0x000000b2 <+20>:
                        rjmp
                                .+0
                                                 ; main+22로 jump
  0x000000b4 <+22>:
                        nop
                                                                                      while{}
  0x000000b6 <+24>:
                                0x1b, r1
                        out
  0x000000b8 <+26>:
                        ldi
                                r18, 0xFF
  0x000000ba <+28>:
                        ldi
                                r19, 0x69
                        ldi
  0x000000bc <+30>:
                                r25, 0x18
  0x000000be <+32>:
                        subi
                                r18, 0x01
  0x000000c0 <+34>:
                        sbci
                                r19, 0x00
  0x000000c2 <+36>:
                        sbci
                                r25, 0x00
  0x000000c4 <+38>:
                        brne
                                .-8
  0x000000c6 <+40>:
                                .+0
                        rjmp
  0x000000c8 <+42>:
                        nop
  0x000000ca <+44>:
                                                ; main+4로 jump
                        rjmp
                                .-42
End of assembler dump.
(gdb)
```

### Register Summary

#### Datasheet 349p~350p

\$24 (\$44)	TCNT2				Timer/Cou	ınter2 (8 Bit)				155
\$23 (\$43)	OCR2		Timer/Counter2 Output Compare Register 155				155			
\$22 (\$42)	OCDR	IDRD/OCDR7	OCDR6	OCDR5	OCDR4	OCDR3	OCDR2	OCDR1	OCDR0	260
\$21 (\$41)	WDTCR	_	_	1	WDCE	WDE	WDP2	WDP1	WDP0	57
\$20 (\$40)	SFIOR	TSM	_	-	-	ACME	PUD	PSR0	PSR321	84, 108, 141, 218
\$1F (\$3F)	EEARH	-	-	-	-		EEPROM Addr	ess Register High		31
\$1E (\$3E)	EEARL			E	EPROM Addres	s Register Low B	yte			31
\$1D (\$3D)	EEDR				EEPROM (	Data Register				31
\$1C (\$3C)	EECR	_	_	-	-	EERIE	EEMWE	EEWE	EERE	31
\$1B (\$3B)	PORTA	PORTA7	PORTA6	PORTA5	PORTA4	PORTA3	PORTA2	PORTA1	PORTA0	84
\$1A (\$3A)	DDRA	DDA7	DDA6	DDA5	DDA4	DDA3	DDA2	DDA1	DDA0	84
\$19 (\$39)	PINA	PINA7	PINA6	PINA5	PINA4	PINA3	PINA2	PINA1	PINA0	84
\$18 (\$38)	PORTB	PORTB7	PORTB6	PORTB5	PORTB4	PORTB3	PORTB2	PORTB1	PORTB0	85
\$17 (\$37)	DDRB	DDB7	DDB6	DDB5	DDB4	DDB3	DDB2	DDB1	DDB0	85
\$16 (\$36)	PINB	PINB7	PINB6	PINB5	PINB4	PINB3	PINB2	PINB1	PINB0	85
\$15 (\$35)	PORTC	PORTC7	PORTC6	PORTC5	PORTC4	PORTC3	PORTC2	PORTC1	PORTC0	85
\$14 (\$34)	DDRC	DDC7	DDC6	DDC5	DDC4	DDC3	DDC2	DDC1	DDC0	85
\$13 (\$33)	PINC	PINC7	PINC6	PINC5	PINC4	PINC3	PINC2	PINC1	PINC0	85
\$12 (\$32)	PORTD	PORTD7	PORTD6	PORTD5	PORTD4	PORTD3	PORTD2	PORTD1	PORTD0	85
\$11 (\$31)	DDRD	DDD7	DDD6	DDD5	DDD4	DDD3	DDD2	DDD1	DDD0	86
\$10 (\$30)	PIND	PIND7	PIND6	PIND5	PIND4	PIND3	PIND2	PIND1	PIND0	86
ADE (ADE)	0000									

```
(gdb) disass main
Dump of assembler code for function main:
   0x0000009e <+0>:
                        ldi
                                r24, 0xFF
  0x000000a0 <+2>:
                                0x1a, r24
                        out
                                                                                 \leftarrow PORTA = 0xFF;
  0x000000a2 <+4>:
                                0x1b, r24
                        out
  0x000000a4 <+6>:
                        ldi
                                r18, 0xFF
  0x000000a6 <+8>:
                        ldi
                                r19, 0x69
  0x000000a8 <+10>:
                        ldi
                                r25, 0x18
  0x000000aa <+12>:
                                r18, 0x01
                        subi
  0x000000ac <+14>:
                        sbci
                                r19, 0x00
  0x000000ae <+16>:
                        sbci
                                r25, 0x00
  0x000000b0 < +18>:
                        brne
                                .-8
  0x000000b2 <+20>:
                        rjmp
                                .+0
                                                 ; main+22로 jump
  0x000000b4 <+22>:
                        nop
                                                                                  - PORTA = 0x00:
  0x000000b6 <+24>:
                                0x1b, r1
                        out
  0x000000b8 <+26>:
                        ldi
                                r18, 0xFF
  0x000000ba <+28>:
                        ldi
                                r19, 0x69
  0x000000bc <+30>:
                        ldi
                                r25, 0x18
  0x000000be <+32>:
                                r18, 0x01
                        subi
  0x000000c0 <+34>:
                        sbci
                                r19, 0x00
  0x000000c2 <+36>:
                        sbci
                                r25, 0x00
  0x000000c4 <+38>:
                        brne
                                .-8
  0x000000c6 <+40>:
                        rjmp
                                .+0
  0x000000c8 <+42>:
                        nop
  0x000000ca <+44>:
                                .-42
                        rjmp
                                                 ; main+4로 jump
End of assembler dump.
(gdb)
```

```
(gdb) disass main
Dump of assembler code for function main:
   0x0000009e <+0>:
                        ldi
                                r24, 0xFF
   0x000000a0 <+2>:
                                0x1a, r24
                        out
   0x000000a2 <+4>:
                        out
                                0x1b, r24
   0x000000a4 <+6>:
                        ldi
                                r18, 0xFF
   0x000000a6 <+8>:
                        ldi
                                r19, 0x69
   0x000000a8 <+10>:
                        ldi
                                r25, 0x18
   0x000000aa <+12>:
                                r18, 0x01
                        subi
                                                                                   _delay_ms(1000);
   0x000000ac <+14>:
                                r19, 0x00
                        sbci
   0x000000ae <+16>:
                        sbci
                                r25, 0x00
   0x000000b0 <+18>:
                        brne
                                .-8
                                                ; main+22로 jump
   0x000000b2 <+20>:
                                .+0
                        rjmp
   0x000000b4 <+22>:
                        nop
   0x000000b6 <+24>:
                                0x1b, r1
                        out
   0x000000b8 <+26>:
                        ldi
                                r18, 0xFF
   0x000000ba <+28>:
                        ldi
                                r19, 0x69
   0x000000bc <+30>:
                                r25, 0x18
                        ldi
                                                                                   _delay_ms(1000);
   0x000000be <+32>:
                                r18, 0x01
                        subi
   0x000000c0 <+34>:
                                r19, 0x00
                        sbci
   0x000000c2 <+36>:
                        sbci
                                r25, 0x00
   0x000000c4 <+38>:
                        brne
                                .-8
   0x000000c6 <+40>:
                                .+0
                                                  main+42로 jump
                        rjmp
   0x000000c8 <+42>:
                        nop
  0x000000ca <+44>:
                        rjmp
                                .-42
                                                ; main+4로 jump
End of assembler dump.
(gdb)
```

### 1초를 만드는 방법

```
MCU의 속도 : 8,000,000hz = 1초에 8백만 clock 소모
⇒ 즉, 8백만 clock을 소모해야 1초가 흐른다.
                      r18, 0xFF ; r18에 0xFF를 저장한다.
0x000000a4 <+6>: ldi
                      r19, 0x69 ; r19에 0x69를 저장한다.
0x000000a6 <+8>: 1di
                                  ; r25에 0x18를 저장한다.
0x000000a8 <+10>: ldi
                      r25, 0x18
                      r18, 0x01 ; r18에서 1을 뺀다.
                subi
0x000000aa <+12>:
                      r19, 0x00 ; r19에서 0-carry를 뺀다.
0x000000ac <+14>:
                sbci
                      r25, 0x00 ; r25에서 0-carry를 뺀다.
0x000000ae <+16>: sbci
0x000000b0 <+18>:
                brne
                      .-8
                                  ; main+12로 branch
```

### 1초를 만드는 방법

```
MCU의 속도 : 8,000,000hz = 1초에 8백만 clock 소모
⇒ 즉, 8백만 clock을 소모해야 1초가 흐른다.
                       r18, 0xFF ; r18에 0xFF를 저장한다.
0x000000a4 <+6>: 1di
                      r19, 0x69 ; r19에 0x69를 저장한다.
0x000000a6 <+8>: Idi
                      r25, 0x18 ; r25에 0x18를 저장한다.
0x000000a8 <+10>: ldi
                       r18, 0x01 ; 1 clock
0x000000aa <+12>: subi
0x000000ac <+14>: sbci
                       r19, 0x00 ; 1 clock
0x000000ae <+16>: sbci
                       r25, 0x00 ; 1 clock
0x000000b0 <+18>:
                brne
                      .-8 ; 2 clock
(0xff(255)+1 * 0x69(105)+1 * 0x1(1)) * 5 = 135,680
(0xff(255)+1 * 0xff(255)+1 * 0x17(23)+1) * 5 = 7,864,320
135,680 + 7,864,320 = 8,000,000
```

### 0x00 주소엔 무엇이?

```
/100i 0x0
 xØ <__vectors>:
                                             ; 0x8c <__trampolines_start>
                     rjmp
                             .+138
0x2 <__vectors+2>:
                     nop
0x4 < vectors+4>:
                     rjmp
                             .+150
                                              ; 0x9c <__vector_9>
0x6 <__vectors+6>:
                     nop
0x8 <__vectors+8>:
                                              ; 0x9c <__vector_9>
                     rjmp
                              . +146
0xa <__vectors+10>: nop
0xc <__vectors+12>: rjmp
                             .+142
                                             ; 0x9c <__vector_9>
Oxe <__vectors+14>: nop
0x10 <__vectors+16>: rjmp
                                             ; 0x9c <__vector_9>
                             .+138
0x12 <__vectors+18>: nop
0x14 <__vectors+20>: rjmp
                                              ; 0x9c <__vector_9>
                             .+134
0x16 <__vectors+22>: nop
0x18 <__vectors+24>: rjmp
                             .+130
                                             ; 0x9c <__vector_9>
0x1a <__vectors+26>: nop
0x1c <__vectors+28>: rjmp
                                              : 0x9c < vector 9>
                             .+126
0x1e <__vectors+30>: nop
0x20 <__vectors+32>: r.jmp
                                              ; 0x9c <__vector_9>
                             .+122
0x22 <__vectors+34>: nop
0x24 <__vectors+36>: r.jmp
                                             ; 0x9c <__vector_9>
                             .+118
0x26 <__vectors+38>: nop
0x28 <__vectors+40>: r.jmp
                                             ; 0x9c <__vector_9>
                             .+114
0x2a <__vectors+42>: nop
0x2c <__vectors+44>: rjmp
                             .+110
                                             ; 0x9c <__vector_9>
0x2e <__vectors+46>: nop
0x30 <__vectors+48>: r.jmp
                                              ; 0x9c <__vector_9>
                             .+106
0x32 <__vectors+50>: nop
0x34 <__vectors+52>: rjmp
                             . +102
                                             ; 0x9c <__vector_9>
0x36 <__vectors+54>: nop
0x38 <__vectors+56>: r.jmp
                                             ; 0x9c <__vector_9>
                              . +98
0x3a <__vectors+58>: nop
0x3c <__vectors+60>: r.jmp
                                             ; 0x9c <__vector_9>
                              . +94
0x3e <__vectors+62>: nop
0x40 <__vectors+64>: rjmp
                              . +90
                                             ; 0x9c <__vector_9>
0x42 <__vectors+66>: nop
0x44 <__vectors+68>: rjmp
                             . +86
                                             ; 0x9c <__vector_9>
0x46 <__vectors+70>: nop
0x48 <__vectors+72>: rjmp
                             . +82
                                             ; 0x9c <__vector_9>
0x4a <__vectors+74>: nop
0x4c <__vectors+76>: r.jmp
                                              ; 0x9c <__vector_9>
                              . +78
0x4e <__vectors+78>: nop
```

### **Interrupt Vectors**

- Datasheet 59p~60p
- interrupt vector : 인터럽트가 발생했을 때, 그 인터럽트를 처리할 수 있는 서비스 루틴들의 주소를 가지고 있는 공간

/ector No.	Program Address <sup>(2)</sup> Source		Interrupt Definition			
1	\$0000 <sup>(1)</sup>	RESET	External Pin, Power-on Reset, Brown-out Reset, Watchdog Reset, and JTAG AVR Reset			
2	\$0002	INT0	External Interrupt Request 0			
3	\$0004	INT1	External Interrupt Request 1			
4	\$0006	INT2	External Interrupt Request 2			
5	\$0008	INT3	External Interrupt Request 3			
6	\$000A	INT4	External Interrupt Request 4			
7	\$000C	INT5	External Interrupt Request 5			
8	\$000E	INT6	External Interrupt Request 6			
9	\$0010	INT7	External Interrupt Request 7			
10	\$0012	TIMER2 COMP	Timer/Counter2 Compare Match			
11	\$0014	TIMER2 OVF	Timer/Counter2 Overflow			
12	\$0016	TIMER1 CAPT	Timer/Counter1 Capture Event			
13	\$0018	TIMER1 COMPA	Timer/Counter1 Compare Match A			
14	\$001A	TIMER1 COMPB	Timer/Counter1 Compare Match B			

### Reset(trampolines\_start) 분석

```
0x8c <__trampolines_start>:
                                           r1, r1 ; xor r1, r1 \Rightarrow 0
                                   eor
0x8e <__trampolines_start+2>:
                                           0x3f, r1; SREG = 0
                                   out
0x90 <__trampolines_start+4>:
                                           r28, 0xFF; r28 = 0xFF (Y-REG)
                                   ldi
                                           r29, 0x10; r29 = 0x10 (Y-REG)
0x92 <__trampolines_start+6>:
                                   ldi
0x94 <__trampolines_start+8>:
                                           0x3e, r29 ; SPH = 0x10
                                   out
                                           0x3d, r28; SPL = 0xFF (SP=0x10FF)
0x96 <__trampolines_start+10>:
                                   out
0x98 <__trampolines_start+12>:
                                rcall
                                           .+4 ; call <main>
0x9a <__trampolines_start+14>:
                                   rjmp
                                           .+48
                                                     ; jmp <exit>
```

- -SREG 상태 레지스터를 0으로 초기화
- -스택 주소를 0x10FF로 초기화
- -Main 함수 호출
- -Main 종료 후 Exit 함수 호출

### Exit 함수 분석

```
0xcc <exit>: cli
0xce <__stop_program>: rjmp .-2 ; 0xcc <__stop_program>
```

- -인터럽트 비활성화
- -무한 루프

# 감사합니다.