# Safety With Soil Fines

The smallest particles can prove deadly, so take precautions to keep yourself safe



Fines particles, smaller than 75  $\mu$ m are dangerous. Fines smaller than 10  $\mu$ m can prove deadly. The following four safety tips can help reduce the dangers of working with these materials:

## 1. Use Proper Personal Protective Equipment

- Use masks for work with an inhalation risk
- Wear gloves when handling toxic material

## 2. Use Proper Transportation Strategies

- Take caution when moving fines, as when dropped, fines can enter the air and be inhaled
- Pouring fines too quickly can also lead to airborne particles

## 3. Create Detailed Safety Plans

- Know the procedures for mitigating risks in experiments
- Avoid unnecessary risks
- Understand possible routes of harmful exposure before starting work

# 4. Use the "Buddy System"

- Handling hazardous materials alone in the lab increases health risks
- Working with at least one other individual increases the likelihood of obtaining help in emergency events.

