USB Ports and Connectors List

Port Count	Name	Туре	Location	Connectors	Mapped?
1	HS02	UBS 2.0 Hub	Front	2	✓
	HS09*	USB 2.0	Front	1 -	
2	SS09	USB 3.0			\checkmark
	HS10*	USB 2.0	Front	1	
3	SS10	USB 3.0			\checkmark
4	HS11	USB 2.0/1.1	Rear	1	✓
5	HS13	USB 2.0/1.1	Rear	1	\checkmark
	HS12	ITE Device	Internal		
6	HS07	4-port USB 2.1/3.1 Hub	Rear	4	\checkmark
7	SS07	4-port 03B 2.1/3.1 Hub			\checkmark
8	HS05	USB 2.0	Rear	1 -	\checkmark
9	SS05	USB 3.2			✓
10	HS06	USB 2.0 Type-C	Rear	1	✓
11	SS06	USB 3.2 Type C			\checkmark
12	HS04	USB 2.0	Rear	1	✓
13	SS04	USB 3.2			\checkmark
14	HS03	Q-Flash Plus Port (for BIOS updates)	Rear	1	\checkmark
15	SS03	USB 3.2			\checkmark

^{*} Port/Connector also works for USB 2.0 Devices

Front and Rear I/O



