USB Ports and Connectors List

Port Count	Name	Туре	Location	Connectors	Mapped?
1	HS02	UBS 2.0 Hub	Front	2	\checkmark
2	HS09	USB 2.0	Front	1 -	\checkmark
3	SS09	USB 3.0			\checkmark
4	HS10	USB 2.0	Front	1	\checkmark
5	SS10	USB 3.0			✓
6	HS11	USB 2.0/1.1	Rear	1	✓
7	HS13	USB 2.0/1.1	Rear	1	✓
	HS12	ITE Device	Internal		
8	HS07	4 m and UCD 0 4 /0 4 Umb	Rear	4	✓
9	SS07	4-port USB 2.1/3.1 Hub			✓
10	HS05	USB 2.0	Rear	1	✓
11	SS05	USB 3.2			✓
	HS06	USB 2.0 Type-C	Rear	1	
	SS06	USB 3.2 Type C			
12	HS04	USB 2.0	Rear	1	✓
13	SS04	USB 3.2			\checkmark
14	HS03	Q-Flash Plus Port (for BIOS updates)	Rear	1	✓
15	SS03	USB 3.2			\checkmark

Front and Rear I/O



