Table of Contents

FEM class HW1	. 1
Exercise No.1	1
Exercise No.2	2

FEM class HW1


In this subroutine 1D stressed beam and axisymmetric heated plate.

Coded by Manuel Diaz, f99543083, IAM, 2013.03.05.

```
clear all; close all; clc;
```


Exercise No.1

```
x = linspace(1,3,40); % Domain
          % Cross section Area
A = 0.01;
           % Young Modulus
E = 10^5;
% Exact Solution
c_1 = 1/1000 + 9/(A*E) - 3*(A+10)/(10*A*E);
c_2 = (A+10)/(10*A*E);
u_exact = c_2*x + c_1 - x.^3/(3*A*E);
s_exact = E*c_2 - x.^2/A;
% Linear Approximation
alpha1_1 = (3*A-100)/(30*A*E);
u1 = 1/1000 + alpha1_1*(x-3);
s1 = E*(alpha1_1*ones(size(x)));
% Parabolic Approximation
alpha2_1 = -(220-3*A)/(30*A*E);
alpha2_2 = -2/(A*E);
u2 = 1/1000 + alpha2_1*(x-3) + alpha2_2*(x-3).^2;
s2 = E*(alpha2_1 + 2*alpha2_2*(x-3));
% Draw Figures
figure(1)
subplot(1,2,1);
hold on; title('Displacement, u(x)')
plot(x,u_exact,'-k'); plot(x,u1,'ok'); plot(x,u2,'sk'); hold off;
xlabel('x'), ylabel('displacement'); legend('exact','linear','quadratic',3)
subplot(1,2,2);
hold on; title('Stress, \sigma(x)')
plot(x,s_exact,'-k'); plot(x,s1,'ok'); plot(x,s2,'sk'); hold off;
xlabel('x'), ylabel('stress'); legend('exact', 'linear', 'quadratic',3)
```



Exercise No.2

```
R = 2/1000; % Radious of plate [m]
r = linspace(0,R,40); % Domain
s = 3.18E9; % Source term [W/m<sup>3</sup>]
k = 15;
             % Conduction constant [W/(m.K)]
C_1 = 0; C_2 = s*R^2/(2*(k+1));
T_{exact} = C_1*r.^(1-1/k)+C_2-s*r.^2/(2*(k+1));
% Linear Approximation
Alpha1_0 = 0;
Alpha1_1 = (2*R*s)/(3*k);
T1 = Alpha1_0 + Alpha1_1*(R-r);
% Quadratic Approximation
Alpha2_0 = 0;
Alpha2_1 = 3*R*s/k;
Alpha2_2 = -7*s/(4*k);
T2 = Alpha2_0 + Alpha2_1*(R-r) + Alpha2_2*(r-R).^2;
% Draw Figure
figure(2)
hold on; title('Plate Temperature, T(r)')
plot(r,T_exact,'-k'); plot(r,T1,'ok'); plot(r,T2,'sk');
xlabel('r'),ylabel('temperature oK');legend('exact','linear','quadratic',1)
```



Published with MATLAB® 7.14