Manufacturer	Model	Hardware Revision	Firmware Version	Chipset	Vulnerable?	ISP	Notes - Testing done with Pixiewps	Туре
Alfa	AIP-W525H	v1		RTL8192CE	Yes		Tested and verified	Router
Arris	DG1670	v1		Ralink	Yes	Time Warner	Tested and verified - TWC Now locks out immediately	Gateway?
Arris	TG1672	v1		Ralink	Yes	Time Warner	Tested and verified - TWC Now locks out immediately	Gateway?
Arris	TG852G	v1		RT3662F	Yes		Tested and verified	Gateway
Arris	TG862G	v1		RT2860	Yes		Tested and verified	
Arris	TG862G	v5		RT3352	Yes	Comcast/Xfinity	Secret PIN found: 42000648 Should work on for all, 10+ confirmed	Gateway
Asus	RT-AC66U	v1		BCM4331/BCM4360	No	•		
Asus	RT-N10E	v1		RTL8196C	Yes		Tested and verified	Rotuer
Asus	RT-N12E	v1		RTL8192CE	Yes		Tested and verified	Router
Asus	RT-N15	v1		RT2880/RT2820	Yes		Tested and verified	
Asus	RT-N56U	v1		RT3092/RT3662	Yes		Tested and verified	
Asus	RT-N66U	v1		BCM4331	No			Router
Belkin	F5D8236-4	v3		RT3052	Yes		Tested and verified	Router
Belkin	F7D1301	v1		BCM5365A1	No			
Belkin	F9K1103	v1		RT3883/RT3092	Yes		Tested and verified	Router
Belkin	F9K1105	v2		RTL8188RE/RTL8192DR	Yes		Tested and verified	Router
Belkin	F9K1110	v1		RT3883	Yes		Tested and verified	Router
Buffalo	WBMR-HP-GN	v1		RT3070	Yes		Tested and verified	DSL/Router
Cisco	DPC3939	v1		BCM3383	Yes/No	Comcast/Xfinity	Possibly HEX to Decimal, ATM thats it	Router
Cisco	DPC3941	v1		AR9381/QCA9880-BR4A	No	Comodouximity	1 obolisty Field Declinar, 71111 triate it	Gateway
Compal	CBN-106-145-065	v1		Realtek	Yes		Tested and verified	Cutcway
Compal	CH6640E	v1		RTL8192CE	Yes		Tested and verified	
D-Link	DIR-501	A1		RTL8188RE	Yes		Tested and verified  Tested and verified	Router
D-Link	DIR-605L	v1		RTL8196C	Yes		Tested and verified - All can be assumed vulnerable	Router
D-Link	DIR-610N	A1		RT5350	Yes		Tested and verified - All call be assumed vulnerable	Router
D-Link	DIR-615	E3		AR9287	No		resteu anu venneu	Router
D-Link	DIR-615	H1		RT3352	Yes		Tested and verified	Router
		A1		RT3092				
D-Link	DIR-626L				Yes		Tested and verified	Router
D-Link D-Link	DIR-655 GO-RT-N150	A1 v1		AR5416/AR2133 RT5350	No Yes	Contologom	Tested and verified	Router
	FON 2303B			RT3052	Yes	Csctelecom	Tested and verified	Router
Edimax		v1						Douter
Encore	ENHWI-3GN3	v1		RT3050	Yes		Tested and verified	Router
EnGenius	ESR6650	v1		RT3050	Yes		Tested and verified	Router
Hitron	CGN2-ROG	4		RT3253	Yes		Tested and verified	0-1
Hitron	CGN3-ROG	v1		Ralink	Yes		Tested and verified	Gateway
Hitron	CGN3ACR			ртосог	Yes		Tested and verified	<b>D</b> (
Hitron	CVE30360	v1		RT3352F	Yes		Tested and verified	Router
Huawei	HG532s	v1		RT5392	Yes	Orange	Tested and verified	Gateway
Huawei	HG566a	v1		RT2860	Yes	Vodafone (Spain)	Tested and verified	Gateway
Linksys	E1000	v1		BCM4716B0	No		T	Router
Linksys	E1700	v1		MT7620A	Yes		Tested and verified	
Linksys	E2500	v1		BCM5358UB0/BCM43236	No			
Linksys	E2500	v2		BCM5358UB0	No		T	Router
Linksys	RE1000	v2		RT5392	Yes		Tested and verified	Repeater
Linksys	WRT160N	v2		RT2880	Yes		Tested and verified	Router
Linksys	WRT1900AC	v1		Marvell 88W8864	No			Router
Linksys	WRT310N	v1		BCM4321/BCM2055	No			Router
Mitrastar	HGW-2501GN-R2	v1?		RT3593	Yes	Movistar-Telefonica	Tested but not verified	Gateway
Motorola	SBG6580	v1		BCM3380/BCM43224	No			Gateway
NETGEAR	JNR3210	v1		RTL8192CE	Yes		Tested and verified	Router

Manufacturer	Model	Hardware Revision	Firmware Version	Chipset	Vulnerable?	ISP	Notes - Testing done with Pixiewps	Туре
NETGEAR	PR2000	v1		MT7620N	Yes		Tested and verified	Repeater
NETGEAR	R6100	v1		AR9344	No			Router
NETGEAR	R6300	v1		BCM4360/BCM4331	No			Router
NETGEAR	R7000	v1		BCM4360	No			Router
NETGEAR	WGR614	v10		BCM5356A1	No			Router
NETGEAR	WN3100RP	v1			No			
NETGEAR	WNDR3400	v1		Broadcom	No			Router
NETGEAR	WNDR3400	v2		BCM5358UB0/BCM43236	No			Router
NETGEAR	WNDR3700	v1		AR9220/AR9223	No			Router
NETGEAR	WNDR3700	v2		AR9220/AR9223	No			Router
NETGEAR	WNDR3700	v3		BCM4718A1/BCM4331	No			Router
NETGEAR	WNDR3700	v4		AR9344/AR9582	No			Router
NETGEAR	WNDR3800	v1		AR9220/AR9223	No			Router
NETGEAR	WNR1000	v3		BCM5356A1	No			RouterRouter
NETGEAR	WNR2000	v2		BCM4716B0	No			Router
NETGEAR	WNR2000	v3		AR9287	No			Router
NETGEAR	WNR2000	v4		AR9341	No			Router
Sitecom	WLM-4600	v1001		RT2860	Yes		Tested and verified	Router
SMC	SMCD3GNV	v1		RT3662	Yes	Comcast/Xfinity	Tested and verified	Gateway
Technicolor	TC8305C	v1		BCM4331	No	Comcast/Xfinity		Gateway
Technicolor	TD5130	v1		RTL8188RE	Yes		Tested and verified	Gateway
Technicolor	TD5130	v2		RTL8672	Yes		Tested and verified	Gateway
Technicolor	TD5130	v3			No			
Teldat	"iRouteur" 1104-W	v1	All are affected	RT2860	Yes	Telefonica	Tested and verified	Gateway
TI (Texas Instruments?)	APDK71	v1			No			
TP-Link	Archer C20i	v1		MT7620A/MT7610E	Yes		Tested and verified	Router
TP-Link	TD-W8951ND		3.0.1 Build 110720 Rel.40612	RT2860	Yes		Tested and verified - Probably all vulnerable	
TP-Link	TL-WDR3500	v1			Yes			
TP-Link	TL-WR1043	v1			No			
TP-Link	TL-WR1043ND	v1			No			
TP-Link	TL-WR740n	v1		AR9285	No			Router
TP-Link	TL-WR740n	v2		AR9285	No			Router
TP-Link	TL-WR841N	v1			No			
TRENDnet	TEW-691GR	v1		RT3883	Yes		Tested and verified	
ZyXEL	C1000Z	v1		BCM63268	No			Router
ZyXEL	P-2812HNU-F3	v1		RT3062	Yes		Tested and verified	DSL/Router
ZyXEL	P-660HN-T1A	v1		RT2860	Yes		Tested and verified	Router
ZyXEL	P-660W-T1	v3			No			
ZyXEL	VMG3312-B10A	v1			No			Router