
Revision	Date	Author	Description		
1	13/05/2017	G.Boschini	First Draft		
2	26/08/2017	G.Boschini	- Updated symbol from library Removed Micro SD card interface Removed Artik 020 USB Debug Removed Artik 020 USB Debug Removed Artik 020 USB Debug Removed CMSL Utag connector Removed MSL Utag connector Removed Battery Backup from Artik Changed Usbary and Camasa connector Changed WiFi+BL Module- Changed WiFi+BL Module- Changed WiFi+BL Module- Changed WiFi+BL Module- Removed Answer Stage St		
3	20/11/2017	G.Boschini	- Updated symbol from library - Removed DSW1 - Removed DSW1 - Removed DSW1 - Replaced IBMT-D connector (123) - Replaced IBMT-D connector with HDMT-A connector - Replaced IBMT-D connector with HDMT-A connector - Replaced BSW5 with Sandisk - Added Power Con/Off LED - Added MAT connection between Artik and CML via FTDI chip - Added MAT connection between Artik and CML via FTDI chip - Added Power switch for palect antenna - Added Power switch for powerdown SV device (USB MOST, HDMT) - Added Power switch for powerdown SV device (USB MOST, HDMT) - Added Power switch for powerdown SV device (USB MOST, HDMT) - Added Power switch for powerdown SV device (USB MOST, HDMT) - Added Power SW DSW DSW DSW DSW DSW DSW DSW DSW DSW		
4	02/01/2018	G.Boschini	- Correct PCB Led SilkScreen		
5	17/01/2018	G.Boschini	- Removed UART Bluetooth connection - Changed IZC bus for RTC, Artik 020, CM3, IO Expander and isolated RTC and Artik bus from IO Expander and CM3 when CM3 is not powered - Modified SV HAT Fower Supply - Enable W. Disable_mPCIE - Removed WiFi clock enable - Added switch for selection of WiFi antennas and removed signal from CM3 - Removed BCGs Led - Removed BCGs Led - Added serial connection from CM3 to Artik - Added SWO connection from CM3 to Artik - Added SWD connection from CM3 to Artik - Moved HDMI Enable and PSW MiFit to IO Expander - Replaced power input connector with black version		
6	06/02/2018	G.Boschini	- Updated symbol from library - Corrected SW-12C met name - Added RGB Led - Removed SWO connection from CM3 to Artik - Moved PON Witi to CM3 - Moved HDWI_LS_OE to 103 of 10 Expander		
7	22/02/2018	G.Boschini	- Removed logo from silkscreen		
8	17/05/2018	G.Boschini	- Added FIN logo on silkscreen - Changed value of R259,R264,C218,C219,C222,C224,C227,C228,C229,C230		
9	10/12/2018	G.Boschini	- Removed Reset Button (FB1) - Removed protection networks of HAT connector (DS11, DS12, DS13, DS14, DS15, DS16, D		
10	31/01/2019	G.Boschini	- Updated symbol from library - Replace LAN9514 with industrial version - Replace RA95 connector with temperature extended version - Added power supply from debug USB - Added RIJI for reset MCUU - Change to mount USB strip connector		







	Project	BALENA FIN	Page name	
halana Ein	Board	BALENA FIN	00 - REVISION	
balenaFin	Designe	r G.Boschini	Approved Approved	
	Project 0	Code 2017-3009	Customer BALENA.IO	
	Internal	Code -	Code -	
Data	Rev.	v. Rev. changes		
Thursday, January 31, 2019	10 :	See Revision Page		1/11
			•	

