

Disassemble and remove the following items from the motor plate assembly. Keep the remaining items for the new assembly.

ITEM NO.	DESCRIPTION	
3	Left Motor Plate with Inserts	1

A


В

	Left Assembly Part Harvesting			
Created by: last edited:				
<u></u>	BY	Joshua Vasquez	1/23/2020	
		SCALE: 1:1	SHEET 3 OF 12	

В

Disassemble and remove the following items from the motor plate assembly. Keep the remaining items for the new assembly.

ITEM NO.	DESCRIPTION	
5	M4 shoulder screw, 12mm-l, 5mm-d	2
6	M3 Buttonhead Screw, 12mm long	4
11	Right Motor Plate with Inserts	1



Α

В

Right Assembly Part Harvesting				
Created by: last edited: Joshua Vasquez 1/23/2020				
		SCALE: 1:1	SHEET 4 OF 12	


2


٨

В

В

В






Α

ITEM NO.	DESCRIPTION	
1	M3 Standoff, 13mm long, 6mm wide	2
2	M3 Buttonhead Screw, 10mm long	2
3	Machined Left Motor Corner Bracket	1

Left Motor Plate Assembly 1/4				
<u></u>	Created by: last edited: Joshua Vasquez 1/23/2020			
		SCALE: 1:1	SHEET 5 OF 12	




Α

ITEM NO.	DESCRIPTION	
4	M5 Buttonhead Screw, 20mm long	4
5	M5 Drop-In T-Nut for 20x20 Extrusion	4
6	Short Motor Corner Plate Spacer with Inserts	1

Left Motor Plate Assembly 2/4				
<u></u>	Created by: last edited: Joshua Vasquez 1/23/2020			
		SCALE: 1:1	SHEET 6 OF 12	

В






2

В

-

В





Α


В


ITEM NO.	DESCRIPTION	QTY.
2	M3 Buttonhead Screw, 10mm long	6
14	M3 Washer	4
15	Stepper Motor with Drive Pulley	1

	Left Motor Plate Assembly 4/4		
Created by: last edited: Joshua Vasquez 1/23/2020			
		SCALE: 1:1	SHEET 8 OF 12

В

В






Α


ITEM NO.	DESCRIPTION	
1	Machined Right Motor Corner Bracket	1
2	M3 Standoff, 13mm long, 6mm wide	2
3	M3 Buttonhead Screw, 10mm long	2


Right Motor Plate Assembly 1/4				
Created by: last edited: Joshua Vasquez 1/23/2020				
		SCALE: 1:1	SHEET 9 OF 12	

В

2 | 1







Right Motor Plate Assembly 2/4			
(C)	()	Created by: Joshua Vasquez	last edited: 1/23/2020
		SCALE: 1:1	SHEET 10 OF 12


2

•

Α

В

2




В


ITEM NO.	DESCRIPTION	
3	20T Idler pulley, 2GT, 5mm bore	1
4	20T toothless idler, 5mm bore	1
5	pulley reinforcement plate for motor	1
6	M3 Buttonhead Screw, 6mm long	2
7	M4 Shoulder Screw, 16mm-l, 5mm-d	2
8	M5 Shim, 0.2mm thick	2
9	OpenBuilds M5 3mm Spacer	2


В

Α



Right Motor Plate Assembly 3/4			
(cc)	•	Created by:	last edited:
	BY	Joshua Vasquez	
		SCALE: 1:1	SHEET 11 OF 12





Α

В

ITEM NO.	DESCRIPTION	QTY.
14	M3 Buttonhead Screw, 10mm long	6
15	Stepper Motor with Drive Pulley	1
16	M3 Washer	4

Right Motor Plate Assembly	4/	4
----------------------------	----	---

В

Α

	Created by:	last edited:	
CC BY	Joshua Vasquez	1/23/2020	
	SCALE: 1:1	SHEET 12 OF 12	