FORTH DISK I/O using 1541

Called by R/w from FORTH

Stack has (flag, blk, addr ...)

flag = O-Write 1- READ

blk = block or screen no.

addr = begining address of 1024 byte block

Also will need a DISK FORMAT command from EDRTH

Use DOS SAVE command @ 9183 for Nw:0

PI= Device #

PZ= START ADDRESS

P3= END ADDRESS+1

NAME @ FNAME (30 Chrs max) SCR

Set up PI, P2, P3, Name = SCR #

Use DOS CMD S: SCR#

Use DOS CMD SAVE

Use DOS LOAD for R/W=1

: RIW ROT OF IF RWO THEN 1 = IF RIWITHEN;

"MOVE FLG TO TOP IF FLG=0 SAVE SCR # X"

1 R/W O SCREATCH SETUR/S SAVE)

" SCRATCH OLD FILE IF THERE IS ONE THEN SETUP & SAUE SCEX"

R/W I SETUP/L LOAD

." LOAD FILE INTO SER . X "

' SETUP/S

" CONFIG TO SAUE, SCRIE TO FNAME @\$135 light & BAGGE,
ADD 1024+1 TO oddr STORE @ \$AGGA, \$08 TO AGGE