Board Modifications

1-9-2003 Della Shu

1. All on-board RAM REMOVED

- 2 FO-F7 decode line taken off board thru E19 to DISK. To Board.
- 3. SYMDOS IN EPROM 2716 at 423 mapped at \$9000
- 4. BASIC Piggy backed IN 2715's at 1122 1121
- 5. RAE IN -2716's at UZZ UZI
- 6. Debug LED added per appendix H-2
- 7. Buffer B7 on PB7 of 6522 @ \$ACOO is wired as an RS232 Input buffer like Q29 on setted port, input to this buffer is jumpered to Tonnector pin 4.
- 8 U27 pin 25 is wired to U5 pin 4 (Allows IRQ by on board 6532 chip)
- 9. Trace cut on UI between pin 4 and 5 on bottom of board.

 Jumper UI-4 to UZ-5, Takes \$\tilde{\pi}_2\$ to 742\$138 decoder

 as recommended by synertek bulliten.
- 10. Jumper plug installed to allow program control of Debug
- 11. External Reset button INSTALLED
- 12, Removed jumper GG-39. Installed jumper GG to 40 (makes terminal use +5 to -12 volt level)