## St.Joseph's College of Engineering St.Joseph's Institute of Technology GE 6757- Total Quality Management Assignment III

## Part A

- 1. What is a Check sheet?
- 2. Define fraction defective (p).
- 3. What is a Histogram?
- 4. What do you mean by measure of central tendency? What are the three measures of central tendency?
- 5. What is Cause and effect diagram? List its uses.
- 6. What is the purpose of a Pareto diagram?
- 7. What is Scatter diagram?
- 8. What is Control chart? What are the types of Control charts?

## Part B

- 1. What is six sigma concept? How can it be effective in a service organization?
- 2. Explain new seven TQM tools with suitable examples.
- 3. Explain Bench marking and its steps.
- 4. Explain the stages of FMEA.