

There are many way to perfect temperature measurement procedures

The most common technique is to transform floating-point numbers to integers using a scaling factor

- 1-Calculate the values beforehand in excel and just store them as integer as a look-up table in code
- 2- Fixed-point decimal calculations.
- 3- Use 32 bit fixed point calculations to get decent results if you attempt to use the polynomial functions.