
04 NOV 21

AERODROME

MOUNT PLEASANT



1. RHAG inset: Rwy 10 - 1476ft, Rwy 28 - 1083ft.

Rwy 05 – 1919ft, Rwy 23 – 1427ft.

Additional RHAG Rwy 10/28 centrally located.

Rwy 10/28. Normal Ops. App cable DE-RIGGED, central cable DE-RIGGED, over-run cable UP. Rwy 05/23. Normal Ops. App cable UP, over-run cable UP, 10 min PNR to raise/lower/de-rig.

2. Circuits. Rwy 05/10 RHC.

AIDU Last Amended 11 NOV

N 100

- 3. Foxtrot twy to main apron not suitable for B747 and AN124/224 due to earth banking and twy shoulder width. Delta twy suitable for small acft only.
- 4. Ground frequencies not routinely monitored.
- 5. Twy E not avbl for arriving heavy air systems. Twy F to be expected for egress from Rwy 28.

AERODROME