
14 JUL 22

UK MOD Crown Copyright 2022. Not AIDU is not responsible for, and claims no right to, the content or accuracy of 3rd party documents/information.



- 1. CAUTION. High risk of bird strikes.
- 2. CAUTION. Rwy 06/24 and Rwy 01/19 concrete ends only liable to be slippery when wet.
- Rwy 01/19 STOL strip markings, HI edge lights, HI and LI thr and end lights, QDM dependent HI edge lights.
- 4. Concrete shoulders Rwy 06/24, 15·24m wide. Rwy 01/19, 7·5m wide.
- **5** Rwy 24 1% up slope in first 1000ft.
- 6. RHAG inset:

Amended 11

Last

N01

- a. Rwy 06 2100ft.
- b. Rwy 24 1600ft.

For normal ops, both cables DOWN.

- 7. Circuits 1000ft QFE. Rwy 06 RHC.
- 8. Slow lane is the South side of Rwy 06/24 and West side of Rwy 01/19.

MARHAM

AERODROME