







































Date	Category	Item
2012.09.27 (V0.12)	General	Clone from MT6589_MT6320_MT6167_MT6628_EMMC_LPDDR2_WG_NO RXD_V0.12.DSN
	Page7	Change RF3236 and TXM control table to SKY77590
2012.10.01 (V0.13)	Page3	Change C338/C343 from 2.2uF -> 4.7uF
2012.10.04 (V0.14)	Page3	Change R323 from 24K -> NC Change R351 from NC -> 39K
2012.10.17 (V0.15)	Common	Change VDD18_PMU to VIO18_PMU Change VDD28_PMU to VIO28_PMU
	22	
	Page3	Update PMIC power spec. table
	Page7	Change U702 pin23 from net TRXB2 to GSM1900 Change U702 pin22 from net TRXB5 to GSM850
	Page9	Add Camera share power notification
	Page11	Change the connection between EMII105 and CON1101
	Page14	Remove Add T-card ESD notification
2012.11.12 (V0.16)	Page2	Remove UCTS1/URTS1 debug trace
	Page3	Remove D301 and C339 reserved for VPA performance originally Remove R330, R331 reserved for VM power boos-strap function (internal pull low for LPDDR2) Remove R307, R309 Remove Pre-Charge LED, Indicator LED and add KEYPAD LED
		Update VM_SEL boot-strap table
		Add 4 shottky diod at VPROC/VDDK/VPA/VM LX pin Remove R333, R326, R325
		Remove C308~C313 LDO Cin
		Change C342 from NC to 10uF (NC)
		Change L307 from CKP25202R2M-T to MDMK2020T2R2MM (NC)
		Change U303, U304 to NC (Reserve for Pulse charger)
	Page4	Add external Audio AMP / internal Audio AMP solution
	Page5	Remove R518~R526 eMMC pull high resistor
		Change C537 from 2.2uF -> 4.7uF Change C523 from 0.1uF -> 1uF
	Page9	Change VOL_UP/DOWN mapping
	Page10	Remove I2S interface of MT6628 (sync to MRG interface)
	_	Remove MT6628 co-clock circuit
	Page11	Change the connection between EMI1105 and CON1101 Remove MHL related feature
		Remove IC_USB description Remove USB common choke (Optional by customer application)
		Change ESD protection device to virastor
	Page15	Remove IC-USB function
	Page16	Remove Gyro sensor
	Page99	Update block diagram
2012.11.15 (V0.17)	Page3	Change D301/D303/D304/D304 value from "Rohm RB521C-30" to "Rohm RB521CS-30"
		Remove R301~R304 MHL/NFC used I2C pull high resistor Remove U303, U304 pulse charger schematic
	Page4	Change description "Speaker (external Audio AMP)" to "Speaker (external Audio AMP to Sub PCB)"
2012.11.19	Page3	Change R328 value from "R / 56 / ohm / 0805/ 1%" to "R / 56 / m / ohm / 0805/ 1%"
(V0.18)		Remove Pulse charger related information
2012.11.23 (V0.19)	Page3	Add Pulse charger
	Page18	Change U1801 value from "FN5405" to "FAN5405"
2012.11.28 (V0.20)	Page2	Connect Baseband CLK26M2 (pin AJ14) to CLK26M1 (pin AJ19)
	Page3	Change VPA current sepc. description from 800mA -> 600mA
2012.12.04 (V0.21)	Page1	Modify MT6589 VPROC_FB (pin AB11) & GND_VPROC_FB (pin AD11) to be floating
	Page3	Remove R349, R350 and let CPU remote sense from bypass cap
	Page18	Change C1808 from 10uF -> 1uF for USB inrush current spec.
2012.12.17 (V0.22)	Page3	Change description C134 form 10uF to 22uF
	Page4	Update Power spec. table  Change description *C431/C405/C406* close to MIC
	Pagel	Change description *C408/C427/C429* close to MIC  Remove R110~R111/R113~R118
2013:01:02 (V1.00)		
	Page3	Change J301 ISINK power to VBAT Add C344/C345/C346/C347 for RF de-sense issue Remove R313
		Remove R342~R347 and share all PMIC LDO input with R341
		Remove R358/R340 and share VRF18_1/VRF18_2/VIO18 bulk input with R339
	Page4	Update J401 external audio amp design
	Page7	Change R703 to 10K
		Change R717 to 24K
		Change C701 to 220pF
	Page11	Remove D1101



This document was created with Win2PDF available at <a href="http://www.daneprairie.com">http://www.daneprairie.com</a>. The unregistered version of Win2PDF is for evaluation or non-commercial use only.