Build Overview:

MECHANICAL MANUFACTURING INSTRUCTIONS

LEVEL SWITCH ASSY – CDU RESERVOIR



CHANGE HISTORY

Date	BPM Rev	Change Details	Updated by
	1	New Issue	JOSEPH AMAD

Prepared By:
JOSEPH R. AMAD
Manufacturing Engineer

Checked By:
IVAN NOWELL PANIQUE
Team Lead

Approved By:
SHERWIN ARIOSTE
Operations Manager

SPECIAL TOOLS

Crimpers CERTICRIMP 2 SAHT UMNL 24-18 AWG

METHOD:

Flow chart of operation steps

SIC preparation
↓
Preparation Tools
↓
Prepare Materials
↓
Complete Operation
↓
Inventory Materials
↓
Operation Check
↓
Inventory tool

Size Hardware	Newton Meter
M2 x 0.4	0.2
M3 x 0.5	0.7
M4 x 0.7	1.6
M5 x 0.8	3.3
M6 x 1.0	5.6
M8 x 1.25	13.5

Torque Rules

- Torque values shown are for steel-to-steel material only.
- Torque all screws and nuts unless otherwise specified.
- Torque table is for reference. See MFE-500-01 for detailed information.

MAN: CERTIFIED OPERATOR, TECHNICIAN

LEVEL SWITCH ASSY – CDU RESERVOIR

1. Obtain qty. 1 Level Switch (638-047-00).
2. Cut wires to a length of 85mm. and strip the ends to 5mm.



3. Crimp pin connectors qty. 3 (634-075-01) onto wires using a standard crimping tool.

MAN: CERTIFIED OPERATOR, TECHNICIAN

LEVEL SWITCH ASSY – CDU RESERVOIR

1. Obtain qty 1 of 3-Position Plug (359-494-03) kit which includes back and front housings.
2. Take the back housing of the plug and Insert the pin connectors into the holes until they are fully seated.
   a. Insert Red wire into P1
   b. Insert Black wire into P2
   c. Insert White wire into P3



MAN: CERTIFIED OPERATOR, TECHNICIAN

LEVEL SWITCH ASSY – CDU RESERVOIR

1. Install the front housing onto the back housing by snapping in place.

2. Install qty. 1 O-ring (361-607-07) over switch bulb making sure its fully seated as shown.

3. Create label and mark with location data as shown.

RESERVOIR
LEVEL
SENSOR

MAN: CERTIFIED OPERATOR, TECHNICIAN

LEVEL SWITCH ASSY – CDU RESERVOIR

1. Create label and mark with part number 633-439-00, Rev * , and date of manufacture
   XXYY
   - Where * is the current revision of the part
   - Where XX defines the year and YY defines the week buil

633-439-00 Rev. *
XXYY

2. Install labels on finished assembly.