## Platform:

SDM660,SDM670, SDM845, MSM8998

## Issue:

QC4 user space codes, we don't release to customer, just release the bin file hvcp\_opti.bin.

If meet charging thermal balance issue or PD issues, need to capture the bin file logs.

#### Method:

# Enable bin file logs:

adb shell setprop persist.hvdcp.log\_level 1
adb shell setprop persist.std\_pd.log\_level 1
adb shell setprop persist.pps.log\_level 1
adb shell setprop persist.therm\_bal.log\_level 1
adb shell setprop persist.ctm.log\_level 1

# PD logs,

cat /sys/class/usbpd/usbpd0/\*
cat /d/ipc\_logging/usb\_pd/log

# Kernel logs,

echo 'file smb-lib.c +p' > /d/dynamic\_debug/control
echo 'file qpnp-smb2.c +p' > /d/dynamic\_debug/control
echo 'file policy\_engine.c +p' > /d/dynamic\_debug/control
echo 14 > /sys/module/qpnp\_smb2/parameters/debug\_mask
echo 8 > /proc/sys/kernel/printk