# Applicable platform:

All platform

### **Issue Description:**


Most modem power cases caused by wrong configurations on call box(CMW 500)


## **Common setting on device:**

- 1. Device can enter sleep in APM mode
- 2. Close data service
- 3. Close auto-rotate, auto sync-up, GPS, BT, NFC
- 4. Use blank card connected with call box(CMW500) to test
- 5. All CS call should be tested under Odbm Tx power (GSM 900 min Tx power is 5dbm)
- 6. All CS call should be tested Mute
- 7. Please press power key to turn off screen, if coved P-sensor to turn off screen will hold wake lock and keep AP awake


## **GSM Talk key setup:**

- 1. All based on standby related setup
- 2. PCL set to 19 means Tx power is 5dbm(Tx power=43-2\*PCL value)
- 3. DTX should be turn off






# Standard power waveform:




### **TDS-CDMA Talk Key setup:**

- 1. All based on standby related setup
- 2. Power Control used close loop




### Standard power waveform:



#### WCDMA Talk Key setup:

- 1. All based on standby related setup
- 2. Power Control used close loop



### Standard power waveform:

