- Close Window
- Print This Page
- Expand All | Collapse All

How to determine wakeup trigger from suspend caused by PMIC IRQ?

Solution Number

00027777

Please Note:

If Qualcomm documentation is referenced in this solution, your access to it is based on your company's

Language Key Words

Detail Information

Solution Title Solution Details

How to determine wakeup trigger from suspend caused by PMIC IRQ?

[366.151054] gic_show_resume_irq: 222 triggered

This debug message in the kernel log indicates that a PMIC SPMI IRQ was the wakeup trigger from suspend.

To enable additional debug message printing use the following cmds.

adb root

adb wait-for-devices

adb shell mount -t debugfs none /sys/kernel/debug

adb shell "echo 8 > /proc/sys/kernel/printk"

adb shell "echo 'func qpnpint_handle_irq +p' > /sys/kernel/debug/dynamic_debug/control"

Once the device wakes up from suspend, messages like the ones below will get printed out.

Example #1:

[26.935784] qpnpint_handle_irq: spec slave = 0 per = 18 irq = 0

slave = 0 indicates that it is PM8941. per = 18 indicates that it is PM8941 peripheral 0x12. If we look this up in the PM8941 register document it corresponds to SMBB_BAT_IF_PERPH. Looking at register 0x1218 indicates that irq = 0 corresponds to the BAT_PRES IRQ.

Example #2:

[23.708495] gpnpint handle irg: spec slave = 0 per = 19 irg = 1

slave = 0 indicates that it is PM8941. per = 19 indicates that it is PM8941 peripheral 0x13. If we look this up in the PM8941 register document it corresponds to SMBB_USB_CHGPTH_PERPH Looking at register 0x1318 indicates that irq = 1 corresponds to the USBIN_VALID IRQ.

Applicable Products

PM8019, PM8110, PM8841, PM8926, PM8941, PM8962, PM8974, PMA8084-1, PMA8084-2