oDesktop

class

init

format

CloseAllWindows AddMessage ClearMessages DeleteProject CloseProject CloseProjectNoForce DoesRegistryValueExist EnableAutoSave ExportOptionsFiles GetActiveProject GetAutoSaveEnabled GetBuildDateTimeString GetDefaultUnit GetDistributedAnalysisMachines GetDistributedAnalysisMachinesForDesignType GetGDIObjectCount GetExeDir GetLibraryDirectory GetLocalizationHelper GetMessages GetPersonalLibDirectory GetProcessID GetProjectDirectory GetProjectList **GetProjects** GetRegistryInt GetRegistryString GetTempDirectory GetScriptingToolsHelper GetSysLibDirectory GetTool GetUserLibDirectory GetVersion LaunchJobMonitor NewProject OpenAndConvertProject **OpenMultipleProjects OpenProject OpenProjectWithConversion** PauseRecording **PauseScript** PageSetup Print QuitApplication RefreshJobMonitor RestoreProjectArchive RestoreWindow ResetLogging ResumeRecording RunACTWizardScript RunProgram RunScriptWithArguments RunScript SelectScheduler SetActiveProject SetActiveProjectByPath SetLibraryDirectory SetProjectDirectory SetRegistryFromFile SetRegistryInt SetRegistryString SetTempDirectory Sleep TileWindows SubmitJob class doc delattr format getattribute hash init reduce reduce ex new __repr setattr sizeof subclasshook __str__ oProject AddDataset AddMaterial AnalyzeAll ChangeProperty ClearMessages CloneMaterial Close CopyDesign CutDesign DeleteDataset DeleteDesign DeleteToolObject EditDataset EditMaterial ExportDataset GetActiveDesign **ExportMaterial GetArrayVariables** GetConfigurableData GetDefinitionManager GetDependentFiles GetDesign GetDesigns GetEDBHandle GetLegacyName GetName GetPath **GetProperties GetPropertyValue** GetTopDesignList GetVariableValue GetVariables **ImportDataset** InsertDesign InsertDesignWithWorkflow InsertToolObject PasteDesignBlock Paste Redo RemoveAllUnusedDefinitions RemoveMaterial RemoveUnusedDefinitions Rename Save SaveAs SaveAsStandAloneProject SaveProjectArchive SetActiveDefinitionEditor SetPropertyValue SetActiveDesign SetVariableValue SimulateAll Undo **UpdateDefinitions**

delattr

new

getattribute

doc

hash

reduce

reduce_ex	repr	setattr
sizeof	str	subclasshook
oDesign		
AddCompInstance	AddDataset	AddModelingProperties
AddOutputVariable	Analyze	AnalyzeAll
AnalyzeAllNominal	ChangePortProperty	ChangeProperty
CopyItemCommand	CreateReport	DCReportGeneration
DeleteCompInstance	DeleteDataset	DeleteDesignInstance
DeleteFieldVariation	DeleteFullVariation	DeleteOutputVariable
DeletePort	DeleteSolutionVariation	DeleteSource
DesignOptions	EditCoSimulationOptions	EditDataset
EditHfssExtents	EditImportData	EditInfiniteArray
EditNotes	EditOptions	EditOutputVariable
EnableSolutionSetup	ExportConvergence	ExportCurrentsData
ExportDesignPoint	ExportForHSpice	ExportForSpice
ExportNMFData	ExportNearFieldData	ExportNetworkData
ExportProfile	ExportReport	GetActiveEditor
GetConfigurableData	GetData	GetDesignType
GetDiagnostics	GetEditor	GetMenuChoices
GetModule	GetName	GetNoteText
GetOutputVariableValue	GetOutputVariables	GetPropHost
GetProperties	GetPropertyValue	GetVariableValue
GetVariables	ImportComponentFile	ImportComponentMappingFile
ImportData	ImportDataFilePath	ImportDataset
InsertDesign	InvalidateAllSolutions	InvalidateSolutions
ModifyMeshAttributes	OverlayCurrents	OverlayFarField
OverlayMesh	OverlayNearField	PasteDesign
PasteItemCommand	Redo	RemoveAllReports
RemoveCircuitElement	RemoveImportData	RemoveModelingProperties
RemoveReport	RenameCircuitElement	RenameDesignInstance
RenameImportData	RenamePort	RenameSource
ReportTemplates	RunToolkit	SetActiveEditor
SetPropertyValue	SetTemperatureSettings	SetVariableValue
SimulateLink	StartAnalysis	StopSimLink
Undo	UpdateSources	ValidateCircuit
ValidateLink	class	delattr
doc	format	getattribute
hash	init	new
reduce	reduce ex	repr

oEditor

__setattr__

subclasshook

Activate AddCircuitRefPort AddLayer AddObject AddPinGroupRefPort Add Ports To All NetsAdd Ports To NetAddRefPort Add Stackup LayerAdd Voltage RegulatorsAlignObjects AlignPorts AssignCircuitRefPort AssignRefPort ChangeLayer Change LayersChangeOptions ChangeProperty ClearLayerMappings ClearRefPort ClearRelative

__sizeof__

__str__

Connect ConnectPortInstancesToPins ConvertPlanetoTrace
ConvertTracetoPlane Copy CopyToPlanarEM

Create3DStructure CreateAutomaticTrace CreateCS

CreateCircle CreateCircleVoid CreateCircuitPort
CreateComponent CreateCurrentSourcePort CreateDCTerminal

CreateDCTerminalComponent CreateEdgePort CreateGroundPortComponent CreateGroupSelected CreateHole CreateInterfaceGround

CreateInterfacePort CreateInterfacePortComponent CreateLine
CreateLineFromPolygon CreateLineVoid CreateMeasure

CreateNPortCreateNetClassCreateObjectFromPolygonCreatePinCreatePinGroupCreatePinGroupPortCreatePinGroupsCreatePolygonCreatePolygonVoid

CreatePortInstancePorts CreatePortsOnComponents CreatePortsOnComponentsByNet

CreateRectangle CreateRectangleVoid CreateText CreateVia CreateTrace CreateViaGroups CreateVoltageSourcePort CutOutSubDesign CreateVoltageProbePort DeactivateShort DeactivateOpen DefeatureObjects DelNetClass Delete DeletePinGroup Disconnect DissolveComponents DumpPolygon

Duplicate DuplicateAcrossLyrs Edit

EditPinGroup EnableComponents EraseMeasurements

ExpandExpandWithPortsExportAcisExportDXFExportGDSIIExportGerberExportImageExportMaterialToHFSSUDPExportNCDrillExportStackupXMLExportStrideExportToHFSSExportToHFSSUDPExportToQ3DFilterObjectList

FindObjects FindObjectsByPoint FindObjectsByPolygon
FlipHorizontal FlipVertical GenerateFacetDataForModel

GeometryCheckAndAutofix GetActiveUnits GetAllLayerNames

GetBBox GetCSObjects GetCompInstanceFromRefDes

GetComponentInfo GetComponentPinInfo GetComponentPins GetEditorName GetMaterialList GetLayerInfo GetNetClassNets GetNetClasses GetNetConnections GetNets GetPolygon GetPolygonDef GetPolygonInfo GetPolygonVoids GetPortInfo GetPortInstances GetProperties **GetPropertyValue** GetSelections GetStackupLayerNames GetUserGeometryList

Group Heal HighlightNet

ImportDXF ImportGDSII ImportStackupXML

Intersect ModifyNetClass Move

PageSetup Paste PasteFullDesign

PinConnectivity PlaceDesign Point

Polygon PositionRelative PushExcitations

RemoveLayer RemovePorts RemovePortsFromAllNets
RemovePortsFromNet RemovePortsOnComponents RemoveVoltageRegulators

ResyncGeometry ReverseLine Rotate
SanitizeLayout Select SelectAll

SelectAllNetViolations SelectFirstViolation SelectNetConnected

SelectPhysicallyConnected SetActiveUnits SetCS

SetHfssExtentsVisibleSetHfssPortsVisibleSetLayerMappingSetMCADInstanceAttributesSetMCADModelOriginSetNetColorSetNetVisibleSetPropertyValueSnap3D

StitchLines Subtract ToggleNetHighlight

ToggleViaPin Ungroup Unite

TT 1 (A11	TI 1 (Nr. 11	II 1 (37 1) D. 1 (
UnselectAll	UpdateModels	UpdateVoltageRegulators
ZoomToFit	class	delattr
doc	format	getattribute
hash	init	new
reduce	reduce_ex	repr
setattr	sizeof	str
subclasshook		
module-Optimetrics		
CopySetup	DeleteSetups	DistributedAnalyzeSetup
EditSetup	EnableSetup	ExportDOELocalSensitivity
ExportDOELocalSensitivityCurve	ExportDOEResponseCurve	ExportDOEResponseCurveSlices
ExportDOEResponseSurface	ExportDXConfigFile	ExportOptimetricsProfile
ExportOptimetricsResult	ExportParametricResults	ExportRespSurfaceMinMaxTable
ExportRespSurfacePlotToFile	Export drametre Results Export Resp Surface Refine Points	ExportRespSurfaceResponsePoints
ExportRespSurfaceVerificationPoints	Generate Variation Data	GetOptimetricResult
GetOptimetricResultRowCount	GetSetupNames	GetSetupNamesByType
ImportSetup		PasteSetup
•	InsertSetup	•
RenameSetup	SolveAllSetup	SolveSetup
class	delattr	doc
format	getattribute	hash
init	new	reduce
reduce_ex	repr	setattr
sizeof	str	subclasshook
module-SolveSetups		
Add	AddMeshOperation	AddSweep
Analyze	AnalyzeSweep	Delete
DeleteMeshOperation	DeleteMeshOperations	DeleteSweep
DisplayMesh	DynamicMeshOverlays	Edit
EditMeshOperation	EditSweep	ExportToHfss
ExportToQ3d	GenerateModelMesh	GetAllSolutionNames
GetSetupData	GetSetups	GetSweepInfo
GetSweeps	Layout3DMeshOverlay	LayoutMeshOverlay
ListVariations	RefreshMeshOverlays	Rename
RenameMeshOperation	RenameSweep	RevertToInitialMesh
ShowMeshErrorDialog	Validate	class
delattr	doc	format
getattribute	hash	init
getatarioute new	reduce	reduce ex
	setattr	sizeof
repr str	subclasshook	
	succassiook	
module-FieldsReporter		
AddMarker	AddMarkerToPlot	AddNamedExpr
AddNamedExpression	CalcOp	CalcRead
•	CalcWrite	CalculatorRead
CalculatorWrite	ChangeGeomSettings	ClcEval
ClcMaterial	ClcMaterialValue	ClearAllMarkers
ClearAllNamedExpr	CopyNamedExprToStack	CreateFieldPlot

DeleteFieldPlot DeleteMarker DeleteNamedExpr DeleteUneditablePlot DoesNamedExpressionExists DumpCalculatorStack EnterComplex EnterComplexVector EnterCoord EnterEdge EnterLine EnterOutputVar EnterPoint EnterQty EnterScalar EnterScalarFunc EnterSurf EnterVector EnterVectorFunc EnterVol ExportFieldPlot ExportMarkerTable ExportOnGrid ExportPlotImageToFile **ExportToFile** GetFieldFolderNames GetFieldPlotNames GetMeshPlotNames GetTopEntryValue HideAntennaParameterOverlay HidePolarPlot HideRadiatedPlotOverlay LoadNamedExpressions ModifyFieldPlot ReassignFieldPlot RenameFieldPlot RenamePlotFolder SaveFieldsPlots SaveNamedExpressions SetFieldPlotSettings SetFieldTypeSettings SetPlotFolderSettings SetPlotsSolutionContext SetPlotsViewSolutionContext ShowAntennaParameterOverlay ShowPolarPlot ShowRadiatedPlotOverlay Test UpdateQuantityFieldsPlots **UpdateAllFieldsPlots** XForm class delattr doc format __getattribute hash init new reduce

module-ReportSetup

reduce ex

sizeof

AddAllEyeMeasurements AddCartesianLimitLine AddCartesianLimitLineFromCurve

setattr

subclasshook

AddCartesianLimitLineFromEquation AddCartesianXMarker AddCartesianYMarker

AddCartesianYMarkerToStack AddDeltaMarker AddMarker
AddNote AddTraceCharacteristics AddTraces
ApplyReportTemplate ChangeProperty ClearAllMarkers

__repr__

str

ClearAllTraceCharacteristics CloneReportsFromDatasetSolution CompareReportDataForRegressionTesting CompareReportDataForRegressionTesting2 CompareTracesForRegressionTesting2

CopyPlotSettings CopyReportDefinitions CopyReportsData
CopyTraceDefinitions CopyTracesData CreateReport

CreateReportOfAllQuantities CreateReportFromFile CreateReportFromTemplate DeleteAllReports **DeleteReports** DeleteTraceCharacteristics **DeleteTraces** DoesSupportTraceCharacteristics DumpAllReportsData DumpReportDataForRegressionTesting EditCartesianXMarker EditCartesianYMarker ExportImageToFile EditMarker ExportEyeMaskViolation ExportReportDataToFile ExportTableToFile ExportToFile ExportUniformPointsToFile GetAllCategories GetAllQuantities

GetAllReportNames GetAvailableDisplayTypes GetAvailableReportTypes
GetAvailableSolutions GetDisplayType GetDynLinkIntrinsicVariables

GetDynLinkQtyData GetDynLinkQtyValueState GetDynLinkTraces

GetDynLinkVariableValues GetPropertyValue GetQtyExpressionsForSourceTrace

GetReportSummaryForRegressionTesting GetReportTraceNames GetSolutionContexts

GroupPlotCurvesByGroupingStrategy ImportIntoReport ImportReportDataIntoReport

MovePlotCurvesToGroup MovePlotCurvesToNewGroup OpenWindowForAllReports

OpenWindowForReports PastePlotSettings PasteReports

PasteReportsWithLegacyNames PasteTraces PasteTracesWithLegacyNames

RenameReport RenameTrace ResetPlotSettings

SavePlotSettingsAsDefault SetLinkOutputTraces UngroupPlotCurvesInGroup

UpdateAllReportsUpdateReportsUpdateTracesUpdateTracesContextAndSweeps__delattr__

doc	format	getattribute
hash	init	new
reduce	reduce ex	
setattr	sizeof	repr str
sctatu subclasshook		su
succiassitook		
module-OutputVariabl	e	
CreateOutputVariable	DeleteOutputVariable	DoesOutputVariableExist
EditOutputVariable	ExportOutputVariables	GetOutputVariableValue
GetOutputVariables	ImportOutputVariables	class
delattr	doc	format
getattribute	hash	init
new	reduce	reduce_ex
repr	setattr	_sizeof
str	subclasshook	
module-UserDefinedSo	lutionModule	
CreateUserDefinedSolution	DeleteUserDefinedSolutions	EditUserDefinedSolution
GetUserDefinedSolutionNames	GetUserDefinedSolutionProperties	class
delattr	doc	format
getattribute	hash	init
s new	reduce	reduce ex
	setattr	sizeof
str	subclasshook	
module-DV		
AddRuleSet	AddRun	DeleteRuleSet
DeleteRun	EditRuleSet	EditRun
RenameRuleSet	RenameRun	RunAllDV
RunAllRuleSetDV	RunDV	class
delattr	doc	format
getattribute	hash	init
new	reduce	reduce_ex
repr	setattr	sizeof
str	subclasshook	
module-Excitations		
Add	AddRefPort	AddRefPortUsingEdges
AlphaNumericCircuitMatrix	AlphaNumericMatrix	ConvertToCoax
CoupleEdgePorts	DecoupleEdgePorts	Delete
DeleteDCIRPort	DeleteExcitation	DeleteProbePortAndVia
DeleteSource	Edit	EditCircuitPort
EditExcitations	GetAllBoundariesList	GetAllCircuitPortsList
GetAllPortsList	LoadDiffPairsFromFile	MultiEdit
RemoveRefPort	Rename	RenameSource
ReorderCircuitMatrix	ReorderMatrix	SaveDiffPairsToFile
SelectInLayout	SetCircuitDiffPairs	SetCircuitExcitations
SetDiffPairs	UpdateSources	class
delattr	doc	format

getattribute	hash	init
new	reduce	reduce_ex
repr	setattr	sizeof
str	subclasshook	