```
clear all; close all; clc;
3(c) - Set 1:
L = [.1 .1 .1 .1 .1 .1 .1 .1 .1];
T = [.1 .1 .1 .1 .1 .1 .1 .1 .1];
[ee1, Jnt] = FK(L, T);
tMat =

      0.6216
      -0.7833
      0
      0.7638

      0.7833
      0.6216
      0
      0.4172

      0
      0
      1.0000
      0

      0
      0
      0
      1.0000

ee =
    0.7638
      0.4172
3(c) - Set 2:
L = [.3 .2 .1 .1 .2 .1 .3 .1 .1];
T = [.4 .6 .2 .5 .1 .7 .3 .2 .1];
[ee2, Jnt] = FK(L, T);
tMat =

      -0.9991
      -0.0416
      0
      -0.1994

      0.0416
      -0.9991
      0
      0.8509

      0
      0
      1.0000
      0

      0
      0
      0
      1.0000

ee =
    -0.1994
     0.8509
```

```
3(c) - Set 3:
L = [.1 .1 .1];
T = [.1 .1 .1];
[ee3, Jnt] = FK(L, T);
tMat =

      0.9553
      -0.2955
      0
      0.2930

      0.2955
      0.9553
      0
      0.0594

      0
      0
      1.0000
      0

      0
      0
      0
      1.0000

ee =
     0.2930
      0.0594
3(c) - Set 4:
L = [.1];
T = [.1];
[ee4, Jnt] = FK(L, T);
tMat =

      0.9950
      -0.0998
      0
      0.0995

      0.0998
      0.9950
      0
      0.0100

      0
      0
      1.0000
      0

      0
      0
      0
      1.0000

ee =
        0.0995
        0.0100
```

0.3623

```
3(c) - Set 5:
L = [.2 .2 .2 .2 .2 .2 .2];
T = [.2 .2 .2 .2 .2 .2 .2];
[ee5, Jnt] = FK(L, T);
tMat =

      0.1700
      -0.9854
      0
      0.8992

      0.9854
      0.1700
      0
      0.9258

      0
      0
      1.0000
      0

      0
      0
      0
      1.0000

ee =
     0.8992
      0.9258
3(c) - Set 6:
L = [.3 .2 .1 .1 .2];
T = [.4 .6 .2 .5 .1];
[ee6, Jnt] = FK(L, T);
tMat =

      -0.2272
      -0.9738
      0
      0.3623

      0.9738
      -0.2272
      0
      0.6723

      0
      0
      1.0000
      0

      0
      0
      0
      1.0000

ee =
```

```
3(c) - Set 7:
[ee7, Jnt] = FK(L, T);
tMat =

      0.2675
      -0.9636
      0
      0.9261

      0.9636
      0.2675
      0
      0.7801

      0
      0
      1.0000
      0

      0
      0
      0
      1.0000

ee =
  0.9261
    0.7801
3(c) - Set 8:
L = [.3 .2 .1 .1 .2 .1 .3 .1 .1 .1 .1];
T = [.4 .6 .2 .5 .1 .7 .3 .2 .1 .1 .1];
[ee8, Jnt] = FK(L, T);
tMat =

    -0.9875
    0.1577
    0
    -0.3980

    -0.1577
    -0.9875
    0
    0.8293

      0 0 1.0000 0
0 0 0 1.0000
ee =
   -0.3980
   0.8293
```