



CITRAJET®

Low-Foaming Liquid Acid Cleaner

Sample Trace Analysis Undiluted Concentrate

ELEMENT	DETECTED	DETECTION LIMIT
Chlorine	NONE	Less than 10.0 PPM
Fluorine	NONE	Less than 10.0 PPM
Bromine	NONE	Less than 10.0 PPM
lodine	NONE	Less than 10.0 PPM
Sulfur	NONE	Less than 30.0 PPM
Chromium	NONE	Less than 1.0 PPM
Lead	NONE	Less than 0.1 PPM
Antimony	NONE	Less than 2.0 PPM
Copper	NONE	Less than 0.5 PPM
Zinc	NONE	Less than 10.0 PPM
Bismuth	NONE	Less than 0.01 PPM
Tin	NONE	Less than 15.0 PPM
Cadmium	NONE	Less than 0.5 PPM
Aluminum	NONE	Less than 3.0 PPM
Sodium	NONE	Less than 20.0 PPM
Silicates	NONE	Less than 10 PPM

Recommended dilution Is 2% (2.5 Oz. CITRAJET per gallon of water). When diluted, the amount of the above chemical traces will of course be diluted.

