



## **CITRANOX**®

**Acid Cleaner and Detergent** 

## **Sample Trace Analysis Undiluted Concentrate**

ELEMENT	DETECTED	<b>DETECTION LIMIT</b>
Chlorine	NONE	Less than 10.0 PPM
Fluorine	NONE	Less Than 10.0 PPM
Bromine	NONE	Less Than 10.0 PPM
lodine	NONE	Less Than 10.0 PPM
Chromium	NONE	Less Than 1.0 PPM
Lead	NONE	Less Than 0.1 PPM
Antimony	NONE	Less Than 2.0 PPM
Copper	NONE	Less Than 0.3 PPM
Zinc	1.4 PPM	Less Than 1.0 PPM
Bismuth	NONE	Less Than 0.01 PPM
Tin	NONE	Less Than 15.0 PPM
Cadmium	NONE	Less Than 0.5 PPM
Aluminum	NONE	Less Than 3.0 PPM
Phosphorus	65 PPM	Less Than 5.0 PPM
Sodium	5.4 PPM	Less Than 1.0 PPM

Recommended dilution is 2% (2.5 oz. CITRANOX per gallon of water). When diluted, the amount of the above chemical traces will of course be diluted.

