
COSC HW 6

6.



8.

10. 1101 1010

```
14.
```

Dout _

21. 70 = 0b0100 1100

Q0 -> Q7

Q0 = 010000000001

Q1 = 101000101000

Q2 = 000101010100

Q3 = 010010000010

Q4 = 111000101001

Q5 = 101101111100

Q6 = 000111010110

Q7 = 000010000011

28.

Q0 = 010000100010000

Q0 _____