


# **Concept Of 4 Hole Multi Spindle for Hole Diameter 20mm with Drill JIG**




#### 5 hole Multispindle for Drill Diameter 10.5mm with Drill Jig




# **Band Saw Machine for Eicher Tractor Drawbar Flat Cutting With Dovetail Slide**



# Indexing Jaw For CNC to Rotate the JOB Without De-clamping it for Machining



#### **Pipe Cutting Machine**



We will mount Gear Box & Motor on plate


Hydraulic Cylinder to give the Feed to cutter

Pneumatic cylinder for clamping


Handle to give liner feed to pipe to pipe forward or reverse

.......


### **Mechanical Press For Straightening**



#### **Grinder Machine Attachment**




## **O-Ring Fitment Tool**



➤ Manual O-Ring
Fitment tool for
fitting the O-Ring in
Shaft

# **Pipe Cold Forging Die**




➤ MS Pipe get conically Cold Forged

### M24 Tap Holder at Drilling Machine




➤ Thread Tapping is done at drilling machine to avoid Tap breakage & improve effeciency

# Rotating Tumbler for Removing Burr of Small Parts





➤ Rotating Tumbler for removing Burr of small parts by rotating it in between granual particals

### **Welding Spatter Removing Machine**



#### **Concept Of 7 Hole Multi Spindle for Hole Diameter 20mm Drilling**





#### **Multi Cutter Machine**

