H3 PLUS Firmware Update Steps

This device requires firmware version 1.0.26 or higher.

1. Connect the H3 Plus to your computer using a Type-C date cable.
   Notice, use the side Type-C port, not the bottom charging one.
2. First, connect the computer to the H3 plus, then hold down the PTT button and the "3" key, then power on.
3. The H3 Plus will automatically enter the firmware upgrade interface, and your computer will recognize the USB device



4. Open “Update App.exe”, then open the xxxxx.fw file.



5. Tick the ”Reset after successful update” option, then click Upgrade.

