Download link:
https://walkietalkiesoftware.com/portal/index/software_detail/id/81.html

The public account for our website:
Email: BusHound@gmail.com
Password: 123456

When you Upgrade Firmware on Odmaster Web

1. Need to use Google Chrome browser
2. It can not use Type C programming cable
3. For Windows, CH340 programming cable needs driver.
   For Mac OS need to use FTDI programming cable.
4. Insert the K-head more tightly
5. H3 Plus has to entered the firmware-flashing mode

Upon inspection, we've found that some H3 plus units have hardware variations, which prevent ODmaster-based upgrades.
For now, please use software for upgrades.
We recommend using a Type-C cable.

Notice:

When programming Odmaster app/web, set BT as the receiver.
Please use Google Chrome when programming or upgrading.
For some operations, refer to the video.

If you have any questions, please contact us immediately.

If it's not too much trouble, we would be incredibly thankful if you could support our efforts by shining a 5 *****re on our product page (Your Order->leave a Re.....).

This is of great importance to us.

Thank you so much for your kindness and support.