PAL Pod Halbach Levitation Controller — Rev A0 — PLACEHOLDER PCB

ISO 7010 W006 magnetic-field warning label goes here (silkscreen or mechanical drawing)

SAFETY-CRITICAL BOARD — Full FMEA / DFMEA / power-on checklist required before energizing coils

4-layer F.Cu 2oz signal / In1.Cu GND / In2.Cu PWR_HIGH_CURRENT / B.Cu 2oz signal — ENIG