Project: SJ2088POE Current Revision: R2M0E2

SJ2088POE Revision History:

Date	Revision	Reason for Change	Changes Implemented
5/12/2020	Iniital Release -> R0M0E0		
04/03/2021	R0M0E0 -> R1M0E1		MIPI rule added and trace updated. C33 removed from NPin Production variant
			COS TELLO TEL TOMATA IN FORMACION VALIDAD
04/21/2021		Slow plug issue with USB type-C	Added 1uF capacitor to VBUS_DET updated PCB and fabrication files
		2) BOM errors	2. Edited parameters for components

Title SJ2088POE				Luxonis Holding 1925 Harmony Park Drive	
Size:	Tabloid	Number: D2088000	Revision:R2M0E2	Westminster, CO 80234	Cannot open file C:\Users\BrianLuxonis\
Date:	21/04/2021	Time: 10:23:08	Sheet 1 of 12	United States	14-11-11-11-11-11-11-11-11-11-11-11-11-1

1 2 3 6



























