1 2 3 4 5


Project: DM0260 Current Revision: R1M0E0


DM0260 Revision History:

Date	Revision	Reason for Change	Changes Implemented
12/30/2020	BG0250TG-> R0M0E0	1) ESD protection 2) FPC connector stronger mechanics 3) Outdated stackup	1) Added protection diodes to MIPI lines 2) Changed FFC with Molex 505278 series 3) Standarized 4L stackup
02/12/2020	R0M0E0 -> R1M1E1	1) Make FPC connectors type and pinout AdulCam standard so that camera modules will be compatible with MD1090FPC 2) Library and components not common w/ LaxonisMaster and some has bigger size footprint than needed	I)Changed FFC connectors to ArduCam standard pinout, updated all connections to the conenctors. CBA can be connected with same side 26pin FFC to DMI 190FFC 2) Updated all componets using LuxonisMaster libraries 3) Removed uncessary components from design (10k pull-ups on LDO enable connected directly) made downsizing of footprints for easier layout
02/12/2020	DM0250_R1M1E1 -> DM0260_R0M0E0	Add support for 33-pin standard PPC connector from Arducam Add support for multiple cameras by option to change the core voltage	Used 33-pin standard FPC connector for CCM With populating either R4 or R5 you can select 1 V05 or 1 V2 core voltage respectively.
02/12/2020	DM0260_R0M0E0 -> DM0260_R1M0E0	1) Correct the error because of unused pads 2) Add GND vias reducing the current loops	Corrected added pads on top/bottomlayer Added GND vias


Title DM026	0		Luxonis Holding 1925 Harmony Park Drive	G
Size: Tabloid	Number:D0000999	Revision:R1M0E0	Westminster, CO 80234	Cannot open file C:\Users\BrianLuxonis\
Date: 19/08/2022	Time: 14:35:19	Sheet 1 of 3	United States	14-14-14-14-14-14-14-14-14-14-14-14-14-1

1 2 3 4 5





Power Supply Sequence & Requirements



- AVDD rising can occur before or after DOVDD rising as long as they are rising before XSHUTDOWN rising XSHUTDOWN is pulled up after AVDD and DOVDD are stable DVDD rises after DOVDD, but before XSHUTDOWN is pulled high

Title	DM026	0		Luxonis Holding 1925 Harmony Park Drive	
Size:	Tabloid	Number:D0000999	Revision:R1M0E0	Westminster, CO 80234	Cannot open file C:\Users\BrianLuxonis\
Date:	19/08/2022	Time: 14:35:19	Sheet 2 of 3	United States	14-1416

2

